MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395
Head Office
1284 South Road Clovelly Park, S.A. 5042
PO Box 8, Melrose Park South Australia 5039
Ph: +61 1300 13 12 11 Fax: +61 1300 55 33 19

24 October 2013

General Letter GL–13-022

To: ***Service Managers (cc Dealer Principals)***

Subject **Product Quality Reporting – Additional Requirement**

Further to General Letter GL-13-004, we advise that a DQR (with photographs attached) must be submitted for any oil/fluid leak repair that is to be claimed as warranty with a repair date on or after November 1st 2013.

The list of "Items to be Reported" has been updated accordingly, i.e. item 9 – Oil/Fluid Leaks has been added.

Reporting Requirements

1. Dealers are required to submit a Dealer Quality Report (DQR) for all of the categories listed under "Items to be Reported" unless:
   1) The concern is subject of a Technical Support Request (refer General Letter GL-13-001).
   2) A Hotline Fix has been issued which indicates that DQR's are not required.
2. The relevant reference number (DQR, TSR or Hotline Fix number) must be entered in the "Notes and Attachments" section of any related warranty claim.
3. Reports must be submitted in accordance with the timelines detailed under "Timelines for Reporting".

Note: Failure to comply with these requirements may result in delays in claim processing or claim rejection.

Items to be Reported

1. **All** potential safety related defects irrespective of whether the defect occurs during or after expiration of the warranty period

   Note: For the purpose of Dealer reporting, any failure or malfunction (actual or alleged) that directly or indirectly affects the safe operation of a vehicle or the safety of the vehicle occupants or a third party should be categorised as a safety related condition and handled accordingly.
   This includes but is not necessarily limited to power train, brake system, suspension, steering, seat belts and SRS system
   If there is any doubt as to whether a condition is safety related or not, Franchisee staff should err on the side of caution and handle and report it as a safety related issue.

Copyright © Mitsubishi Motors Australia Limited
Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. 2: This General Letter forms part of the Service Procedure Manual

2. Repairs with a total repair cost exceeding $1,100.
3. Concerns identified on new models during the first 6 months after wholesale launch.
4. Defects which occur after a known countermeasure effective point.
5. Customer complaint conditions which cannot be resolved by applying normal recommended repair methods.
6. Any condition which the Franchisee considers warrants further investigation by MMAL.
7. Repetitive pre delivery or customer complaint items, including any conditions that are considered to be a characteristic of the model, yet in the Franchisee's opinion are affecting customer satisfaction and should be investigated by MMAL.
8. When instructed to report cases of a particular condition by Hotline Fix or other MMAL communication.
9. Oil/fluid leaks including but not limited to leaks from the following:
    - Engine
    - Transmission/transaxle
    - Power steering
    - Brake system
    - Front or rear axle
    - Shock absorbers

Note: When reporting oil leaks, photographs of suitable resolution and focus that clearly show the location and extent of the leak must be attached.

Timelines for Reporting

Category 1 reports must be reported on the day that the vehicle is presented to the Dealer Service Department.

Category 2 – 9 reports must be submitted within 5 working days of the repair being completed.

The relevant pages in the Service Procedure Manual will be updated and issued in the near future.

Your cooperation in ensuring that all relevant staff are notified of and comply with the new procedures is anticipated and appreciated.

Yours sincerely,
Mitsubishi Motors Australia Limited

D. R. Budden

Head of National Service