MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395
Head Office
1284 South Road Clovelly Park, S.A. 5042
PO Box 8, Melrose Park South Australia 5039
Ph: +61 1300 13 12 11 Fax: +61 1300 55 33 19

18 July 2016

General Letter GL–16-028

To: ***Service Managers (cc Dealer Principals).***

Subject ***Service Campaign 020116 Parts Holding Requirements Pre and Post Failure***

This General Letter is being issued to Dealers to advise of the parts holding requirements for long and short engines. This information covers both failures in regards to the 020116 campaign and post campaign.

MMAL can advise that it is necessary to keep the **engine block only** for the above described failures. Other components associated with the long and short engine assembly do not need to be held if it is the result of 020116 campaign and the post campaigns failures.

In the following situation please hold the engine block as follows.

1. Failure in campaign – 30 days
2. Failure post campaign – 90 days As per Warranty Policy & Procedures APPENDIX A4-C: WARRANTY AUDIT STANDARDS.

Packaging such as the wooden box etc. may also be discarded.

Please note **Clear photos of the engine number and engine block surface are required** as described in GL-16-016.

Thank you for your understanding in this matter.

Yours sincerely,
Mitsubishi Motors Australia Limited



Michael Miller
Manager, Field Service.

Copyright © Mitsubishi Motors Australia Limited
Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. 2: This General Letter forms part of the Service Procedure Manual