SDA1 General Letter

Subject	**SDA1 Troubleshooting Guide**		
Applicable model(s)	MR Triton (Select Models)	Bulletin Ref	MMAL-25148
Service Group	54 Chassis Electrical	Latest Revision Issued	Rev A 9/12/2025

Correction/Process

MMAL, in collaboration with Alpine Electronics of Australia, has developed an alternative audio unit to replace SDA1 units in cases of **repeated** failures. Please follow the updated diagnostic procedure outlined below when assessing SDA1 audio units.

If a customer has previously received a replacement SDA1 unit (either refurbished or new) and reports a subsequent issue, begin by replicating the reported fault and refer to the troubleshooting guide below. Once the fault is confirmed, **obtain Customer consent to replace Kenwood unit with Alpine unit.**

A Submit a MiDealer Assist case for approval to replace the unit. On approval MMAL will add the vehicle to service campaign 020220, and the Dealer orders the alternate Alpine system to be dispatched.

This guide is designed to assist with diagnosing and resolving unit failures that occur within standard operating conditions. It does not cover issues arising from circumstances outside normal operation, including but not limited to physical damage, individual compatibility conflicts, or isolated incidents such as screen freezes.

A Please refer to the "SDA1 Troubleshooting Guide" attached to this General Letter.

MR Triton MY18-25 ALPINE iLX-507Ai Infotainment Head Unit

The Alpine iLX-507Ai has been designed to meet or surpass the performance of the current SDA1 audio unit. This new system offers a convenient plug-and-play installation, with all necessary brackets and wiring harnesses included in the kit along with a new microphone that must be fitted. Additionally, a customer user manual tailored to the new unit will be provided and should replace the factory manual during installation.

Post Installation Troubleshooting Guide & Support

Post installation of the Alpine audio unit, please refer to the Alpine Infotainment in Triton MR Troubleshooting Guide in the event there is an issue with the unit.


If the issue cannot be resolved using the steps outlined in the guide, please contact the Alpine Service Department directly via email, ensuring all relevant information specified in the Troubleshooting Guide is included.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Mitsubishi Internal

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Subject	**SDA1 Troubleshooting Guide**		
Applicable model(s)	MR Triton (Select Models)	Bulletin Ref	MMAL-25148
Service Group	54 Chassis Electrical	Latest Revision Issued	Rev A 9/12/2025

MR TRITON MY18-25 ALPINE iLX-507Ai INFOTAINMENT HEAD UNIT - SPARE PARTS



Warranty Terms (when diagnosing connectivity issues)

> To the maximum extent permitted by applicable law, Mitsubishi Motors makes no representations or warranties that the product will operate and work properly in connection with or with the customer's device, equipment, smartphone, and any application and software in the product, and only the customer will be responsible for performance, functionality, connectivity with the customer's device, equipment and smartphone, and any application and software in the product, and all repairs to the customer's device, equipment and smartphone and any other losses and damages actually or allegedly caused by the product and any application and software in the product.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Mitsubishi Internal

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.