MiDisplay General Letter

Subject	**MiDisplay General Letter**		
Applicable model(s)	MR Triton (Select Models)	Bulletin Ref	MMAL-25206
Service Group	54 Chassis Electrical	Latest Revision Issued	Rev B 20/08/2026

Correction/Process

MMAL, in collaboration with Alpine Electronics of Australia, has developed an alternative audio unit to replace MiDisplay units in cases of **repeated** failures. Please follow the updated diagnostic procedure outlined below when assessing MiDisplay audio units.

If a customer has either:

- Previously received a replacement MiDisplay unit (either refurbished or new) and reports a subsequent issue; or
- Reported multiple concerns (documented on RO's) with the original unit.

Begin by replicating the reported fault and refer to the troubleshooting guide below. Once the fault is confirmed, **obtain Customer consent to replace MiDisplay unit with Alpine unit.**

Submit a MiDealer Assist case for approval to replace the unit. On approval MMAL will add the vehicle to service campaign 020225, and the Dealer orders the alternate Alpine system to be dispatched.

This guide is designed to assist with diagnosing and resolving unit failures that occur within standard operating conditions. It does not cover issues arising from circumstances outside normal operation, including but not limited to physical damage, individual compatibility conflicts, or isolated incidents such as screen freezes.

Please refer to the "MiDisplay Troubleshooting Guide" attached to this General Letter.

MR Triton MY19-23 ALPINE iLX-507Ai Infotainment Head Unit

The Alpine iLX-507Ai has been designed to meet or surpass the performance of the current MiDisplay audio unit. This new system offers a convenient plug-and-play installation.

For non GLX models - Alpine unit, new microphone and external GPS antenna will be supplied.

B For GLX models only - Alpine unit, new microphone, external GPS antenna and GLX harness will be supplied (until harness stock is depleted).

Additionally, a customer user manual tailored to the new unit will be provided and should replace the MiDisplay manual during installation.

Post Installation Troubleshooting Guide & Support

Post installation of the Alpine audio unit, please refer to the Alpine Infotainment in Triton MR Troubleshooting Guide in the event there is an issue with the unit.

If the issue cannot be resolved using the steps outlined in the guide, please contact the Alpine Service Department directly via email, ensuring all relevant information specified in the Troubleshooting Guide is included.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Mitsubishi Internal


Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

MiDisplay General Letter


Subject	**MiDisplay General Letter**			
Applicable model(s)	MR Triton (Select Models)	Bulletin Ref	MMAL-25206	
Service Group	54 Chassis Electrical	Latest Revision Issued	Rev B 20/08/2026	

For ALL Models

MR TRITON MY19-23 ALPINE iLX-507Ai INFOTAINMENT HEAD UNIT - SPARE PARTS



B **Plus Harness for GLX models only (until stock is depleted)**



Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Mitsubishi Internal

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Subject	**MiDisplay General Letter**		
Applicable model(s)	MR Triton (Select Models)	Bulletin Ref	MMAL-25206
Service Group	54 Chassis Electrical	Latest Revision Issued	Rev B 20/08/2026

Warranty Terms (when diagnosing connectivity issues)

To the maximum extent permitted by applicable law, Mitsubishi Motors makes no representations or warranties that the product will operate and work properly in connection with or with the customer's device, equipment, smartphone, and any application and software in the product, and only the customer will be responsible for performance, functionality, connectivity with the customer's device, equipment and smartphone, and any application and software in the product, and all repairs to the customer's device, equipment and smartphone and any other losses and damages actually or allegedly caused by the product and any application and software in the product.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Mitsubishi Internal

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.