Hotline Fix – MR54-002

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

Printed versions of this document may be out of date, check the online version.

Subject

Poor call quality (voice echo) on Mi-Display units.

Issued

31/10/2023

Previous Versions

None

Group

54 – Chassis Electrical

MMAL Reference

N/A

Applicable Vehicles

MR Triton

Phenomenon

Some Mi-Display users experience voice echoing during phone calls.

Cause

Inadequate Mi-Display software.

Production Fix

Updated software was implemented in all Ports of Entry (Mi-Display fitment locations) by 18/10/2023.

Field Fix/Action

On a customer complaint basis, check the status of Service Campaign 020200 on the vehicle – Is it outstanding?

- **Yes**.
  Complete Service Campaign 020200 as per the campaign documents and claim as per the campaign.
- **No**.
  Reflash the Mi-Display unit as per the attached instructions and claim as per the "Warranty Information" section of this Hotline Fix.

Parts Information

N/A.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

Copyright © Mitsubishi Motors Australia Limited

Hotline Fix – MR54-002

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

Printed versions of this document may be out of date, check the online version.

Warranty Information

Claim Details	
Claim Type	Warranty (YC01)
Position Code	545013
Complaint Code	55
Circumstance Code	As advised by customer
Diagnosis Code	5D
Claim Items	
Main Labour Operation	545013 00
Labour Qty	1
Labour Time	0.3 hour
Spare part material - Causal Part	Reflash
Quantity	1

Standard warranty terms and conditions apply.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

Copyright © Mitsubishi Motors Australia Limited