MMAL WARRANTY INFORMATION BULLETIN

Bulletin Subject	**Correct Use of Position Codes for Sublet and Actual Time Claims**		
Applicable model(s)	All		
Notice Category	**Claim Submission**	MMAL Reference	**WIB2026-03**
Service Group	00 General	Issue Date	10/07/2026
Claim Type	All	Effective Date	06/07/2026

Attention

Fixed Operations Managers, Service Managers & Advisors, All Service & Warranty Personnel

Overview

MMAL has identified an increase in warranty claims where **Workshop Allowance (001010)** and **Sublet Handling Allowance (001020)** position codes are being incorrectly used to claim actual labour time or sublet repair costs.

To improve claim accuracy, the Warranty Portal has been updated to prevent these allowance position codes from being used with non-permitted work codes. As a result these will only be available as Main Labour Operations with the following configuration:

- **Position Code 001010 - Work Code WA (Workshop Allowance)**
- **Position Code 001020 - Work Code HA (Sublet Handling Allowance)**

This bulletin clarifies the correct coding requirements for **actual time repairs, sublet repairs** and **allowances.**

Claim Requirements

Main Labour Operation 001010WA – Workshop Allowance

- Main Labour Operation 001010 is reserved exclusively for the Workshop (Vehicle Preparation) Allowance.
- This allowance covers eligible workshop administration and vehicle preparation activities in accordance with MMAL policy.

Main Labour Operation 001020HA – Sublet Handling Allowance

- Main Labour Operation 001020 is reserved exclusively for the Sublet Handling Allowance.
- This allowance reimburses eligible time incurred by a productive staff member when delivering and/or collecting a vehicle or assembly from a third-party repairer.
- Dealers may claim up to **1.0 hour** (in 0.1-hour increments), provided the claim is supported by productive staff clock times.

Claiming Actual Time Repairs

Where an actual time claim is required:

- Select Item Type **Actual Time**
- Use the Position Code applicable to the area of the vehicle being repaired.
- **Work Code 99** will be applied .
- Record the actual repair time in accordance with MMAL policy.

Claiming Sublet Repair Costs

Sublet repair costs must be claimed as follows:

- Select Item Type **External Activity**
- Use the Position Code that most closely describes the repair performed.
- **Work Code LT** will be applied .
- Enter the sublet invoice value **excluding GST**.

Note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. This WIB forms part of the Warranty Policy & Procedure Manual . Details are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.

Mitsubishi Internal

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**Correct Use of Position Codes for Sublet and Actual Time Claims**		
Applicable model(s)	All		
Notice Category	**Claim Submission**	MMAL Reference	**WIB2026-03**
Service Group	00 General	Issue Date	10/07/2026
Claim Type	All	Effective Date	06/07/2026

Important
The Sublet Handling Allowance is separate from the sublet repair cost.

Reference Information

Refer to the SPM & WPPM for detailed information on the requirements for each item.
Dealers should review these manuals to ensure correct claiming procedures are followed and claims are supported by the required documentation.

Simple Rule
The same principle applies to both sublet repairs and actual time claims—the Position Code must reflect the repair being performed (unless otherwise advised by MMAL).

Purpose	Position Code	Work Code	Conditions
Workshop Allowance	001010	WA	Once per RO (conditions apply)
Sublet Handling Allowance	001020	HA	Once per RO. Supported by DMS Tech clock times
Actual Time Repair	Applicable repair position code	99	Supported by DMS Tech clock times
Sublet Repair Cost (less GST)	Applicable repair position code	LT	Supported by Repair Invoice

Quick Tip

Ctrl+F will allow you to search the WPPM and SPM e.g. “sublet”.

Claims submitted with incorrect or inadequate information may be rejected, reversed, or returned for correction. Dealers are encouraged to review their claiming practices to ensure compliance with MMAL Warranty Policies and Procedures.

Abbreviations

SPM - Service Procedure Manual
WPPM - Warranty Policies & Procedures Manual

Yours sincerely,

Fiona Lamond
Warranty Administration Manager

Note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. This WIB forms part of the Warranty Policy & Procedure Manual . Details are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Mitsubishi Internal

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.