WARRANTY INFORMATION BULLETIN

WIB 2005-01 8/02/2005

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Recall Number 010021

Subject: TH/TJ & KH/KJ Verada Fuel Pipe Corrosion Inspection

Our Quality Assurance Department has notified us that they have a sufficient number of replaced fuel pipes for inspection. There is no need for dealers to return any more faulty pipes. The Warranty Disposition List will instruct dealers to destroy any pipes that have been replaced in the process of carrying out recall 010021.

Subject: SERVICE CLAIM AUTHORITIES (SCA's)

When applying to the Customer Assistance Centre or Regional Offices for Service Claim Authorities (SCA's) please take care with claim numbers and claim suffix (hash) numbers. We are experiencing a large number of instances where issued Service Claim Authorities have the wrong claim number and or the wrong job number. If this occurs **please do not submit another claim** to match the authority in the system. The correct procedure is to contact the Customer Assistance Centre or the Regional Office and have the authority number changed so that it matches the claim in the warranty system.

WIS System Error

We have been made aware of a system error with the current version of the Warranty Information System Disc version IV. When submitting a two or more part claim only the first part is being successfully transmitted to the MMAL. If dealers have warranty claims with two or more part's for transmission to MMAL then they should revert to the Click & Add system for those claims until a fix is available.

Parts Return Procedure

Parts that are the subject of a warranty claim must be clean of OIL, PETROL, COOLANT, BRAKE FLUID, & GREASE. We recommend that failed parts be returned to MMAL in the packaging that the new part was removed from. Dealers should treat warranty parts as if they were new parts. We believe it necessary to re-emphasise the need to recap Air Conditioning components prior to return to MMAL. If the discharge & suction fittings of compressors are not capped, they become contaminated during transit. Oil may also leak from A/C components when not correctly capped. Accordingly, we re-affirm that receipt of incorrectly packaged parts could result in the warranty claim being reversed. Please refer to the Warranty Procedure Manual page 45

Ian K. Matthews
Warranty Manager
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039