WARRANTY INFORMATION BULLETIN

WIB 2005-03 25/02/2005

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

New Procedure When Claiming For Exchange Front and Rear DVD Unit's.

To assist in tracking Warranty Claims, there is a new procedure in place for claiming the exchange failed DVD unit.

If a vehicle requires a front or rear DVD unit to be exchanged as part of a warranty claim, MMAL will pay for the removal and the fitting of the exchange unit. The correct part number to be used when submitting a Warranty Claim for a failed DVD unit is,

The front DVD unit XDVDFRONT

The rear DVD unit XDVDREAR

Ian K. Matthews
Warranty Manager
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039