WARRANTY INFORMATION BULLETIN

WIB 2005-06 03/05/2005

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Disposition List's

To assist the Warranty Department in part's returns, please complete and fax the disposition list to MMAL Warranty Administration on (08) 8275 2496 as soon as possible after each payment run.

Procedure When Claiming For Exchange Front and Rear DVD Unit's.

To assist in tracking Warranty Claims, there is a new procedure in place for claiming the failed DVD unit.

If a vehicle requires a front or rear DVD unit to be exchanged as part of a warranty claim, MMAL will pay for the removal and the fitting of the exchange unit. The correct part number to be used when submitting a Warranty Claim for a failed DVD unit is,

The front DVD unit **XDVDFRONT** The Rear DVD unit is **XDVDREAR**

Recall 010018 Lancer tailgate gas strut replacement

When carrying out the 010018 recall please be aware that the labour work code has to be either

11 for the strut replacement
20 for the strut replacement and reinforcement (4 locations) 7.3 hours
40 for the strut replacement and reinforcement (body side only) 4.5 hours

Claiming **LT** as a work code in the labour section is incorrect.

Procedure for claiming replacement keys

In some cases the information on DEACON regarding key numbers is inaccurate. If a key has been cut and it is not correct due to incorrect key numbers then the replacement key must be claimed as a parts claim, claim type P.

Ian K. Matthews
Warranty Manager
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039