ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Warranty Information System (WIS 5)

Please find a copy of the Warranty Information System (WIS) version 5 enclosed in this week's mail-out. You will also find enclosed a copy on the invoice for $55.00, which is the cost of the WIS version 5, including GST.

WIS version 5 includes many enhancements that have been requested by warranty administration staff at dealerships and should prove easier to use. WIS 5 now allows multi-part claims to be successfully submitted. There is also extra data on the CG Lancer. When installing WIS 5 you may have to contact Infomedia on 1811 810 130 to obtain a password.

Return of Used Fuel Tanks

It has been brought to our attention by our warranty parts return storeman that some fuel tanks are not being returned using the correct procedure. As this is a safety issue, please ensure that the fuel tanks are properly cleaned, free of any remaining fuel and properly sealed prior to transporting.

General Letter W16 dated March 2000 outlines the correct steps required to transport fuel tanks. Please refer to this document before sending the fuel tanks if unsure of the correct procedure.

Procedure for Claiming Rental Vehicles

Effective immediately, when claiming for the hire of a rental vehicle, dealers must claim the hire of the rental vehicle on separate claims. The same RO number should be used for both claims. This will mean that dealers will need to submit a claim for the fault on one claim job number and then on a separate claim job number submit a claim for the rental vehicle.

When claiming for the rental vehicle, the claim details must be exactly the same as those of the claim for the original repair. That is, the VIN, repair date, odometer and quality information must all match the claim for the original repair. The parts section of the claim will be NFP and the labour section will have 'RENTAC' for the position code and 'AR' as the work code and then the amount of the rental.

As all rental vehicles require an authority, the authorisation must be placed against the claim with the rent-a-car on it. If the claim for the original repair also requires an authority, then an authority must be placed against both claims.

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039

Any claims currently submitted in the warranty system with a rental vehicle, will not be required to be amended to conform to this new procedure, but effective immediately any new claims will be required to be submitted in this format. Any claims not submitted in this format after the 31st of May 2005 will be returned for correction or backed out for correction if paid.

Recall 010018 – CC Lancer Wagon Tailgate Gas Strut Rework

Due to the age of the vehicles and the nature of the repair there have been instances of consequential damage when repairing some of these vehicles. If there is a shortfall between the time allowed by MMAL to perform this repair and the amount charged by the sublet repairer, then the shortfall may be claimed to reimburse the dealer.

The procedure to claim this is as follows. In the labour section of the claim on the first labour line the position code is 010018 and the work code is 11, 20 or 40 with the applicable allocated time for each procedure. Then on a separate labour line the position code is 010018 and the work code 99 is used and the amount will be the difference between what MMAL allows and what the sublet invoice is charging. Comments will need to be made in the remarks section of the claim detailing what has happened and why the additional amount is required.

If this additional procedure is required, then it is not a requirement to have the claim authorised unless the claim as a whole exceeds the current $2500.00 limit.

Claiming for "Incorrect Build"

Before commencing any work on a vehicle to return it to correct build check the product profile to ensure that that is in fact not the correct build. Work carried out to a vehicle that takes it away from the correct build condition will not be able to be claimed as warranty.

For example all TW Magnas and Veradas built in 2005 with 16" alloys have a steel wheel for the spare. This is the correct build condition. Warranty claims for replacing the steel spare wheel with an alloy one will not be honoured.



Ian K. Matthews
Warranty Manager
Aftersales, Sales & Marketing

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
E-mail: mmal_warranty_admin@mmal.com.au
Address: Level 2A, Mark Oliphant Building
Laffer Drive, Bedford Park
South Australia 5042