MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2006-12 10/07/2007
REVISION 2

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

This bulletin supersedes the previous bulletin WIB-2006-12 REVISION 1 dated 24/10/2006.

Rectification without Replacing Causal Part

If a repair is done to a vehicle and the cause part has been repaired and not replaced, then the word 'REPAIRED' should be used as the cause part with a zero dollar value. If other parts are required to complete the repair, then these should be itemised in the parts section of the claim together with the word 'REPAIRED'.

Please note that this procedure is applicable for all claims except where instructed otherwise. For example, if a recall or service campaign notification advises specific instructions to complete the claim, then these instructions should be followed as outlined in the letter.

Please refer to the procedure below:

- **Quality Code Information:** Use the position code that best relates to the repaired cause part.
- **Cause Part:** The cause part will be the word 'REPAIRED' and will have a zero dollar value when listed in the parts section of the claim.
- **Labour Operation Codes:** The labour operation codes used will reflect the work performed to repair the vehicle.

Example:

If the body (front) wiring harness is determined to be faulty causing a warranty claim to be raised, and the wiring harness was repaired and not replaced, then the warranty claim details would be shown as follows:

Quality Code Information
Position code: 543542 - BODY (FRONT) HARNESS (WIRING HARNESS B)

Cause Part
REPAIRED

Parts List

SUPERSEDED BY WIB 2009-01

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
e-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039

01	PA	REPAIRED	$00.00

Labour Operation Codes

01	LA	543542	99	$$$.$$ (Actual time to repair the fault X labour rate)

Claim Remarks

If a 99 work code is used in the labour operation, put comments in to this section to accurately detail what has been repaired and why.

This procedure supersedes the previous procedure outlined in WIB-2005-11 dated 26/08/2005 under the heading 'NFP as a Cause Part'. Please note that WIB-2005-11 has been modified and is now referred to as WIB-2005-11 REVISION 1.



Ian K. Matthews
Manager, Warranty
Aftersales, Sales & Marketing

SUPERSEDED BY
WIB 2009-01

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
E-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039