MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2010-04 24/06/2010

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Warranty Index X99999

This Warranty Bulletin describes the meaning of warranty index X99999.

This warranty index advises that special conditions may apply to the vehicle's warranty.

If a vehicle with this warranty index is presented at a dealership by a customer with a request for warranty work, dealers should contact MMAL Warranty Department for more information.

Dealers should not commit to, or deny warranty work on these vehicles before discussing with MMAL.

MMAL Warranty Department contact details are shown below.

All warranty work on a vehicle with this warranty index will require authorisation PRIOR to work commencing. Application for a Service Claim Authority (SCA) can be submitted via the on-line SCA Request system contained in the Dealer Extranet. In some cases this will also require an inspection of the vehicle by the relevant MMAL staff.

As a reminder, a description of all warranty indexes can be found from the Warranty Information Bulletin WIB-2007-04 or the Quick Reference Guide, Quick Ref 31.

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:

Warranty Telephone:	(08) 8275 2367	**e-mail:**	warrantyadmin@mmal.com.au mmal_warranty_admin@mmal.com.au
Fax:	(08) 8275 2496	**Address:**	1284 South Road Clovelly Park SA 5042 PO Box 8 Melrose Park SA 5039