MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2010-09 17/12/2010

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

380 Window Regulators

This Warranty Bulletin is to advise dealers that until further notice, all failed 380 (DB model) window regulators are to be held in dealership warranty stores.

MMAL require that as from the date of this bulletin all failed 380 window regulators must be held until further notice. This instruction applies to all 380 model window regulators currently held as well as future failures. This request is for all 380 models only and does not apply to failed window regulators on other models. All other models only require the failed window regulators to be held for the normal 90 day period from claim payment date.

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:

Warranty Telephone:	(08) 8275 2367	**e-mail:**	warrantyadmin@mmal.com.au mmal_warranty_admin@mmal.com.au
Fax:	(08) 8275 2496	**Address:**	1284 South Road Clovelly Park SA 5042 PO Box 8 Melrose Park SA 5039