MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2011-06 07/10/2011

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Warranty Part Return - 1542A117 - 4M41 Inlet Manifold (Triton and Pajero)

This Warranty Bulletin is to inform dealers to return all failed inlet manifolds (part number 1542A117) to Fluiddrive.

Effective from the date of this bulletin, dealers are requested to return all failed inlet manifolds (part number 1542A117) that are currently held in dealer warranty stores to Fluiddrive. All future failures of this part must also be returned to Fluiddrive until instructed otherwise. The details of how and where these parts are to be returned are as follows:

- Contact TNT on 131150 and request the driver to bring a blank TNT con note. Use the TNT account number 21628821 and write “MWTY” in the “Your Ref No” field. Do not use a pre-printed con note.
- Ensure that the part to be returned is correctly tagged with all vehicle and claim information and the part is packaged appropriately so that it is not damaged in transit (Refer WIB-2005-08).
- Address the part return to:
  Fluiddrive Automotive Technologies Pty Ltd
  70 Raglan Street
  Preston, Vic 3072

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Ian K. Matthews
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:

Warranty Telephone:	(08) 8275 2367	**e-mail:**	warrantyadmin@mmal.com.au mmal_warranty_admin@mmal.com.au
Fax:	(08) 8275 2496	**Address:**	1284 South Road Clovelly Park SA 5042 PO Box 8 Melrose Park SA 5039