MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2012-14 9/10/2012

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGER/WARRANTY ADMINISTRATORS

Submitting a DQR Report for Leaks

If Dealers are repairing a vehicle that has a leak and the cause of that leak is a part that can't be returned to MMAL for inspection (eg a seal or a gasket), then Dealers must take photos of the leak if they are submitting a DQR report.

If a DQR report is submitted for a leak, then please attach all photos of the leak to the DQR report that is submitted.

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.

Neale Clarke
Manager, Warranty
Corporate Quality

To contact Warranty Payments Administration:
Warranty Telephone: (08) 8275 2367
e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039