MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2013-16 08/08/2013

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

SRS Part Replacement and Collection

THIS BULLETIN HAS BEEN CANCELLED. REFER TO WIB-2013-21

CANCELLED

MMAL Warranty has been requested by Mitsubishi Motors Japan (MMC) to return some failed parts relating to SRS for MN Triton and PB Challenger only. In addition to the return of these parts, MMC require concise remarks on the claims submitted pertaining to the replaced SRS parts and the remarks must be compiled in a specific format. This requirement is effective as at the date of this bulletin.

There are two scenarios for which the failed parts must be returned and claimed with remarks in this specific format. If the MIL light is on and any of the SRS codes B1421, B1431, B1441, B1451, B1604, and B1610 are displayed and either scenario A or scenario B below has been performed.

Scenario A
If the vehicle is equipped with curtain air bags and the following parts were replaced:
1) Floor harness
2) Roof harness

Scenario B
If the vehicle is NOT equipped with curtain air bags and the following part was replaced:
1) Floor harness

If dealers have a failure that meets either of the above scenarios then the failed parts must be returned to MMAL using the following instructions:

Return Address: Mitsubishi Motors Australia Ltd.
1284 South Road,
Clovelly Park, SA 5042
Attention: Yoshi Tatewaki

Instructions on how to return the parts to MMAL can be located on the dealer portal via the following steps: **Knowledge > Service (Data) > Warranty > Returned Parts Procedure**

Please Note: Do not send the parts to MMAL's Warranty Department, but send them to the

To contact Warranty Payments Administration:
Warranty Telephone: (08) 8275 2367
e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039

attention of Yoshi Tatewaki.

When submitting a claim for either of the above scenarios dealers must ensure that the remarks section of the claim are completed in a specific format and that format is as shown below.

REMARKS
SRS PART REPLACEMENT SCENARIO A OR B
THE REMAINING LINES OF TEXT SHOULD BE USED
TO ELABORATE ON THE QUALITY CODING WHERE
MORE DETAIL WOULD BE OF ASSISTANCE TO THE
INVESTIGATING TECHNICIAN IN JAPAN.

SRS Part Replacement Scenario A or B MUST be entered on the first line of the remarks.

The first line of the remarks must have "SRS Part Replacement scenario A or B" to indicate the SRS part replacement and which scenario was applicable to the repair.
Then on the remaining lines a clear description to elaborate on the quality coding used should be given to assist the investigating technicians in Japan.

To assist dealer's with the quality coding on their claim, the Position codes, Diagnosis and Customer Complaint codes may be applicable, but not limited to the following:

Position Codes
543542 – Body (Front) Harness
543544 – Roof Harness

Diagnosis Codes	**Customer Complaint Codes**
27 - Open circuit	16 - Warning lamp on
34 - Fatigued	30 - Ineffective

The information entered on the claim in conjunction with the returned parts will be used by MMC to assist with the improvement of these parts in the future, which is why MMAL request that the remarks be clear and concise and in this specific format.

If the claim details are also for an existing hotline fix and the hot line fix advises that specific details must be entered in the remarks, then those details must also be entered in the remarks together with the above and preferably at the end of the remarks.



Ian Matthews
Manager, Warranty
Corporate Quality

CANCELLED

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: (08) 8275 2367
Fax: (08) 8275 2496
E-mail: mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039