MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2014-16 30/09/2014

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

Triton Canopy Photos

This Warranty Bulletin is to advise dealers of MMAL's requirements when replacing or repairing a Triton canopy.

Following a request from the vendor, effective from the date of this bulletin, all Triton canopy claims must be supported with photos taken to show the defect.

Photos must be appropriately sized and sent by email to the email address at the bottom of this bulletin. The email must contain the SAP warranty claim number so MMAL's warranty staff can attach the photos to the claim (dealers are currently unable to attach photos to warranty claims).

Photos must be as clear as possible and show the defect to support the warranty claim.

Dealers should also familiarise themselves with warranty bulletin WIB-2011-01 which outlines MMAL's requirements for claim remarks on all Triton canopy replacements and repairs.

These requirements are in addition to any other requirements to supply supporting information, such as DQR, SCA Request, etc.

Failure to adhere to the above requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if this procedure is not followed.



Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:
Warranty Telephone: 1300130099 option 2
option 4

e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au

Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039