MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2015-05 5/05/2015

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

Hotline Fix Procedures

This bulletin is to remind Dealers about claiming hotline fix repairs correctly.

MMAL has observed an increase in the number of hotline fix repairs that are not being claimed exactly as stated in the current hotline fix notification.

From time to time hotline fix procedures are amended and reissued. Please ensure that the current hotline fix procedure is used. The latest version of the hotline fix is always available on the Dealer Portal.

When creating a claim for a hotline fix repair, please check that all requirements have been met. Ensure all warranty claim information has been correctly completed before submitting the claim.

The hotline fix identified with the highest error rate is ML52-003/MN52-001/PB52-001 – SRS Warning Lamp Illuminated with DTC's logged. Some of the common errors identified on this hotline fix are:

- DTC codes omitted from the claim remarks.
- The wrong labour operation code for the model and part number combination used.
- The wrong position code for the number of harnesses replaced (Floor only or Floor and Roof).

Failure to adhere to hotline fix requirements may result in a claim not being paid or reversed at a later date. The claim must also meet audit requirements and could be reversed at audit if the hotline fix procedure is not followed.

Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:
Warranty Telephone: 1300130099 option 2
option 4

e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au

Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039