WIB-2016-06 Update to Campaign Claim System Attachment

Installation Process:

NOTE: Before making any changes to your computer check with your local IT support.


1. Download the appropriate file for your system from the Portal
    a. Two versions are available
        i. Access Version is used if you have Microsoft Access installed on your system
        ii. Runtime Version is used if you do NOT have Microsoft Access installed on your system
2. The file can be found at:

Knowledge >Service (Data) > Warranty Applications > Campaign Claim System > V1.01


3. Locate the files used for the current application on your computer.
    - These will usually be in C:\Program Files\MMAL
    - Check with your IT person if you are unsure, or if the files were custom installed to a different location
4. Create a new folder called “Old Versions” or “V1” (The name is not important as long as you can identify it later)
5. Cut the file called “Campaign Claim System_fe”. It may have an extension of “.accdb” or “.accdr” depending on your system settings
6. Paste the file into the folder you created in step 4
7. Go to your desktop and run the program from the shortcut.

Changes in Version 1.01

1. “Add New Repair Order” screen has been simplified (see screenshot below)




2. The default Coolant amount has been changed to “0”



It is now necessary for you to add the amount of coolant used as recorded by the Technician on the Repair Order.

NOTE: This will be the total amount of coolant added not just the amount added on Step 1 of the Working Procedure. The amount must be supported by technician recordings on the Repair Order.

The following Warning will appear if you do not change the coolant when required.



3. Revised Working Procedure

The Working Procedure has been updated to bring it in line with “020116 4D56 Hi-Power Overheat – Working procedure (revision 3)”. See below for an example.


Campaign 020116 Working Procedure

MITSUBISHI MOTORS

Test

Reference Number	Odometer	Repair Order	Job Number	Service Date
565320	5423	ML12345	A	6/06/2016

VIN MMACNKB40BD003953



This Working Procedure must be attached to the Repair Order

Printed 17/06/2016 11:31:04 AM