MITSUBISHI MOTORS
Drive your Ambition

WARRANTY INFORMATION BULLETIN

WIB 2018-02 17/08/2018

This Bulletin Forms Part of the Warranty Procedure Manual.

ATTN: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

Subject: Dealer VIN and Odometer Discrepancy Process

MMAL have been processing a large number of VIN/Odometer discrepancy requests for corrections, which is causing a lot of claims to be held up for submission and processing.

Dealers must review their booking in processes to confirm the correct vehicle (VIN), odometer and customer details are entered onto the Repair Order (RO). Dealer must also have a further confirmation by the Technician, Foreman or Workshop Controller prior to any repair work.

Dealers must never rely on the MMAL Portal or the Dealer DMS for correct vehicle information (registrations numbers, odometer readings or customer details) for the submission of any warranty or recall claim/s.

In any cases of warranty claim VIN / Odometer Discrepancy, MMAL advise that the following process must be adopted:


- Dealer must confirm the DMS (RO), Vehicle and Customer information are consistent and correct and match the MMAL Portal.
- If the claim error is created by:

1. **the reporting Dealer,**
   - Dealer raises a request for correction direct to Warranty Administration using email warrantyadmin@mmal.com.au with a copy of RO and other supporting documents.
   - MMAL Warranty Administration will take actions as required.
2. **by another Dealer,**
   - Dealer raises a request for correction direct to Warranty Administration using email warrantyadmin@mmal.com.au with a copy of RO and other supporting documents.
   - Warranty Administration will contact State Aftersales Manager to inform of a VIN / Odometer discrepancy with another dealer(s). Dealer/s will need to work with State Aftersales Manager to supply (Warranty Administration) photos (where possible) and scanned images of the following (but not limited to) from the claim relating to the repair:
     - Rego number plate (Photo)
     - VIN stamping (Photo)
     - Odometer reading (Photo)
     - Customer Name and Address (Dealer to make direct contact with customer)
     - RO Front and Back (Scanned Image)
     - Claim and/or SCA (SAP numbers)
     - Conflicting claim number and Dealer (if known)
     - Information detailing the exact area of concern – ie VIN or ODO incorrect
     - Any other information that will clearly identify the vehicle VIN or Odometer changes eg. new instrument cluster installation, registration history, etc
   - State Aftersales Manager will investigate the Dealer enquiry when another dealer is involved to obtain required documentation (Please ensure with enquiries relating to other Dealers you cc your State Aftersales Manager on all email to Warranty Administration). State Aftersales Manager will advise MMAL Warranty Administration of the course of action required by e-mail once all applicable documentation is available to resolve.
   - MMAL Warranty Administration will take actions as required.

Copyright © Mitsubishi Motors Australia Limited Please Note: 1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. 2: This Warranty Information Bulletin forms part of the Warranty Procedure Manual. 3: Details contained in this WIB and Attachments are current at the time of publication. MMAL however, reserves the right to make changes at any time without prior notice or obligation

To contact Warranty Administration: e-mail: warrantyadmin@mmal.com.au

Note: All emails to Warranty Administration/State Aftersales Manager must include “Dealer Code, SAP Claim Number (if applicable), and Odometer or VIN Discrepancy” in the email subject heading (refer example below).
All email correspondence must only relate to one claim or VIN.



Yours sincerely,

Yoshi Tatewaki
Manager, Warranty Enhancement Project
Mitsubishi Motors Australia Limited