MITSUBISHI MOTORS
Drive your Ambition

MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Tonsley Boulevard, Tonsley, SA, 5042
PO Box 8, Melrose Park, SA, 5039
Ph: +61 1300 13 12 11

WIB-2020-05

6th November 2020

Attention: Service Managers, Service & Warranty Personnel

Subject: Repair Only Claims – Work Code 00

Dear Ladies and Gentlemen,

For some time the Operation Code Manual has shown two similar operations, often with identical times, but with different work codes

- work code "00" for Removal and Installation and
- work code "10" for Replacement.

MMAL have previously advised dealers to refrain from using operations with work code "00".

MMAL have recently implemented some system changes that will now allow the use of both work codes.

The correct use of each operation is important to ensure the correct information is supplied and to prevent delays in claim processing and payment.

If applicable to the repair performed, we now request dealers to use the appropriate work code ("00" or "10") in order to accurately identify the work performed to complete the repair.

Selection of the correct operation code should be determined as follows

- Work code 00 should be used when you do a repair only (i.e. where the original part was refitted to the vehicle and the cause part is nominated as REPAIRED.)
- Work code 10 should be used where the causal part/s are replaced (i.e. new component/s fitted).

Failure to adhere to the above requirement may result in delays to claim processing or payment or review/adjustment of previous claim payments.

Yours sincerely,

Fiona Lamond
Warranty Administration Manager