MMAL WARRANTY INFORMATION BULLETIN

MITSUBISHI MOTORS

Bulletin Subject	**Coolant seepage/leakage from core plug at rear of cylinder head on 4N15 Engine.**		
Applicable model(s)	**Refer Technical Bulletin MQ/MR/QE/QF14-001**		
Notice Category	**Hotline fix**	MMAL Reference	**WIB2025-03**
Service Group	14 - Engine Cooling	Issue Date	14/04/2025
Claim Type	SCA/Warranty	Effective Date	Per Hotline Revision A

Attention

Fixed Operations Managers, Service Managers & Advisors, All Service & Warranty Personnel

Overview

To expedite the repair of vehicles (in warranty) that meet the conditions in Hotline Fix MQ/MR/QE/QF14-001, MMAL advises dealers to follow the process detailed below.

Once the "Repair Check Sheet" requirements are met, the repair can proceed without delay. **The SCA should be submitted after the repair is completed,** unless cylinder block distortion exceeds specification or engine damage is evident then the SCA is required before additional work is undertaken.

Note: process flow is included at the end of this bulletin.

Claim Requirements

Refer to the "Repair Check Sheet" included with the Hotline documentation.

Obtain **ALL** required information, photos and measurements **BEFORE** submitting the SCA.

A. If the measured block surface is within the specification and NO resultant damage to the engine is identified order required parts and PROCEED with the repair.

B. ⚠ If cylinder block distortion exceeds specification or engine damage is evident **STOP**. Submit SCA with ALL documentation and measurements. **DO NOT** proceed until MMAL approval is given.

SCA submission MUST include ALL required information listed below

1. Photo of welch plug
2. Completed "Repair Check Sheet"
3. Freeze Frame Data (FFD) / DTC
4. Photo of cylinder block measurement
5. Photo of manifold measurement
6. Include Hotline Fix number in the claim remarks
7. Any additional parts or labour needed to complete the repair must include supporting evidence.

NOTE 1: ALL measurements must be taken using an **engineering straight edge.** No other straight edge will be accepted e.g. wood, steel rules, tube stock etc

NOTE 2: Sublet costs for valve changeover are included in the hotline labour coding.

Note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. This WIB forms part of the Warranty Policy & Procedure Manual . Details are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version. Mitsubishi Internal

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.


Bulletin Subject	**Coolant seepage/leakage from core plug at rear of cylinder head on 4N15 Engine.**		
Applicable model(s)	**Refer Technical Bulletin MQ/MR/QE/QF14-001**		
Notice Category	**Hotline fix**	MMAL Reference	**WIB2025-03**
Service Group	14 - Engine Cooling	Issue Date	14/04/2025
Claim Type	SCA/Warranty	Effective Date	Per Hotline Revision A

Reference Information

> This bulletin should be read in conjunction with Hotline Fix MQ/MR/QE/QF14-001 (available on the MMAL portal) which provides detailed repair requirements.

Quick Tip

> If the dealer determines that the vehicle is covered under the hotline, they **can start work without submitting an SCA**. However, the **SCA MUST be submitted after the work is done**. Incomplete SCA submissions cannot be processed, which delays the decision until all required information is provided to MMAL.



Yours sincerely,

Fiona Lamond
Warranty Administration Manager

Note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. This WIB forms part of the Warranty Policy & Procedure Manual . Details are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version. Mitsubishi Internal

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.