HOTLINE FIX


Group: 52 – Interior and SRS	**Original Date: 22nd February 2017**	**No. XB52-002**
Model: XB ASX	**Subject: Shifter surround rattling on rough roads.**	
Revised on ..... (date) **Revised on** ..... (date) **Revised on** ..... (date)	Y Oda, Deputy Director, Aftersales	
MMAL Ref P4560	**Document consists of 2 pages.**	

(1) **Subject:** Shifter surround rattling on rough roads.

(2) **Possible Cause:** During installation at the factory, it is possible that the retaining clip will become deformed and lose tension, allowing surround to rattle whilst driving on rough surfaces.

(3) **Improvement:** The installation process was modified at assembly line to ensure that no deformation of retaining clip occurs.

(4) **Field Fix/Action:** On a customer complaint basis, please replace the shifter surround with a new item, as per the instructions below, and referring to the relevant workshop manual.



(5) **Parts and Warranty Information:**

(See overleaf)

Standard warranty terms and conditions apply.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

XB52-002			
Claim Header	**Claim Type**	**ZC01**	
	Item 1	**Item Type**	**Spare Part Material**
		Part Number	**As per CAPS**
		Quantity	**1**
		Part Causing Damage	☑
		Claimed Amount	**System Pricing**
		Position Code	**231118**
		Complaint	**81**
		Circumstance	**As per customer complaint.**
		Diagnosis Code	**48**
	Item 2	**Item Type**	**Labour Value**
		Labour Operation	**231118 10**
		Labour Allowance	**As per LOTS time.**