Hotline Fix – ZL54-003, QE54-004, YA54-005, ZK54-006, XC54-002, NX54-003, MQ54-004, MR54-001

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

Printed versions of this document may be out of date, check the online version.

Subject

SDA freezing due to residue on touch panel.

Issued

04/11/2021 – Revision A

Previous Versions

5/3/2020 – Original

Group

54 – Chassis Electrical

MMAL Reference

NA

Applicable Vehicles

All with SDA1.



Disclaimer: The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer internal use only. It must not be provided or supplied to third parties.
Copyright © Mitsubishi Motors Australia Limited

Hotline Fix – ZL54-003, QE54-004, YA54-005, ZK54-006, XC54-002, NX54-003, MQ54-004, MR54-001

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

Printed versions of this document may be out of date, check the online version.

Possible Cause

Residue on touch panel.

Field Fix/Action

MMAL has been advised by the exchange unit supplier that many exchange units are being returned with residual build up of grease/grime on the touch panel of the SDA, and has advised that this may cause the SDA unit to register false touch inputs, which may contribute to a screen freeze concern.

If a customer presents a vehicle with this concern, please clean any residual build up from the touch panel with a soft, dry cloth (such as a commercially available microfiber cloth), as per the SDA handbook.

Warranty Information

Not applicable for this concern. Information only.

Disclaimer: The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer internal use only. It must not be provided or supplied to third parties.
Copyright © Mitsubishi Motors Australia Limited