

維修建議要正視 檢查維修莫遲疑

Don't Ignore Repair Advice
Inspect and Repair Immediately

聯合辦事處優化處理楼宇漏水檢測程序
Enhancing the Inspection and Testing Procedures
for Handling Water Seepage in Buildings by the Joint Office

- 新增以外線熱感應器以加強偵測熱源水滲漏
(Increase Thermography used to reinforce the screening of source of seepage)



- 業主無須向業主發出「建議修葺通知」，業主
在指定時間內自行檢查和維修
(A recommendation letter will be issued to the owner of the upper
unit requesting the inspection and repair within a specified
time frame)

- 如沒有發現任何漏痕跡，聯合辦事處將關閉儀器，並向上樓單位
業主收短租期費用
(If water seepage persists after the decision, the joint office
will conduct investigation and recover the assessment cost
incurred from the owner of the upper unit)



維修建議要正視 檢查維修莫遲疑

Don't Ignore Repair Advice
Inspect and Repair Immediately

聯合辦事處優化處理楼宇漏水檢測程序
Enhancing the Inspection and Testing Procedures
for Handling Water Seepage in Buildings by the Joint Office

- 新增以外線熱感應器以加強偵測熱源水滲漏
(Increase Thermography used to reinforce the screening of source of seepage)



- 業主無須向業主發出「建議修葺通知」，業主
在指定時間內自行檢查和維修
(A recommendation letter will be issued to the owner of the upper
unit requesting the inspection and repair within a specified
time frame)

