
Maintenance Procedure No. MP900

Page 1 of 1

TASK DESCRIPTION			
TEST HIGH VOLTAGE CABINET INDICATOR LAMPS			
BUILDER'S OR VENDOR'S MAINTENANCE INSTRUCTIONS			
MPI LOCOMOTIVE MAINTENANCE MANUAL, SECTION 9			
SPECIAL TOOLS REQUIRED:			
RELATED MAINTENANCE PROCEDURES MODIFICATIONS, POINTERS, ETC.			
SAFETY PRECAUTIONS:			
CONTRACTOR TO ASSUME RESPONSIBILITY FOR SAFETY RULES AND COMPLIANCE.			
PREPARATION:			

PROCEDURE

1. Press the front of each indicator lamp on the engine control panel in the electrical cabinet. Replace any bulb which fails to properly function.



DATE OF FIRST ISSUE	September 2007	AUTHORIZED BY:
REVISION 1	August 2009	TITLE: Manager, Rail Equipment