Maintenance Procedure No. P230

Page 1 of 1

TASK DESCRIPTION			
CHECK OPERATION OF AC1 AND AC2 CONTACTORS FROM RIGHT SIDE, LEFT SIDE AND BOTH SIDES TOGETHER.			
BUILDER'S OR VENDOR'S MAINTENANCE INSTRUCTIONS			
Caterpillar Master Inspection Data Book			
SPECIAL TOOLS REQUIRED:			
RELATED MAINTENANCE PROCEDURES MODIFICATIONS, POINTERS, ETC.			
SAFETY PRECAUTIONS:			
CONTRACTOR TO ASSUME RESPONSIBILITY FOR SAFETY RULES AND COMPLIANCE.			
PREPARATION:			

PROCEDURE

- 1 Ensure trainline complete indicator light in the locomotive cab is on.
- 2 Place both the left and right HEP cutout switches in the down position.
- 3 Press the HEP on push button.
- 4 Ensure the R.H. HEP ON and L.H HEP ON indicators lights are lit.
- 5 Place the right HEP cutout switch in the up position.
- 6 Check the right hand indicator lights to ensure that the R.H HEP ON indicator light has gone out and the HEP CUT-OUT indicator light is ON.
- 7 Repeat steps 5 and 6 for the left side.

DATE OF FIRST ISSUE	May 1997	AUTHORIZED BY:
REVISION 0		TITLE: Manager, Rail Equipment