Inspection Report: RPT-2025-09-28-23A97A

Inspected Item:

damage_type: Crack severity: Critical

action_required: Immediate Replacement photo_filename: IMG_20250928_12345.jpg

inspector_name: A. Verma inspector_id: INSP-2043 vendor: RailTech Industries

batch: BATCH-4821

location: Jaipur Substation A

timestamp: 2025-09-28T11:15:00+05:30

Al Analysis:

condition_score: 20

predicted_failure_risk: Immediate risk of failure; replacement required

vendor_score: ALERT: RailTech Industries batch BATCH-4821 has 25% higher failure rate than av

Work Order:

priority_level: Critical

action: Immediate Replacement spare_part_sku: BOLT-M10-A

assigned_to: Jaipur Maintenance Division

status: Pending

Supervisor Approval:

Supervisor Signature:

Date: 2025-09-28