

Servicedokumentation

Umrüstinformation Nr. 00000020UI

LWL/TKD-Baj/05.11.11

Retrofit information on the subject of:

Temperature too warm

Models: FKUv 161. Index 20 to 21G

FKUv 1660 Index 20 to 21G FKUv 1662 Index 20 to 21F

All versions

Fault profile: The interior temperature deviates from the displayed temperature.

The real temperature in the appliance is much colder than the displayed or the

setted temperature.

Retrofit: Appliances may already be changed over according to 37201100Sl_gb.

In this case please note the label next to the type plate!

This label (7083 453) contains the information that the retrofit kit is

mounted on the appliance.

Following items in the retrofit kit are available as spare parts:

name	Spare part number
clip	7433 233

Hinweis

Beiliegendes Etikett neben oder unterhalb dem Typenschild aufkleben

instruction

Stick on the attached adhesive label next to or underneath the type plate

7081 667

Ergänzende Information zu den Typenschilddaten:

- 9590 309 eingebaut -

Additional information to the data on the type plate:

- 9590 309 built in -

7083 453