

Motor Maintenance Report

Motor Health Summary

Recent non-normal events: 0

Recent monitor count: 5

Recent maintenance alerts: 11

Recent emergency stops: 0

Latest score: None

Detected Pattern

Pattern: mixed

Confidence: 0.75

Evidence

- Repeated vibration-related abnormality
- Temperature elevated or changing quickly
- Current/load behavior changed across recent events

Risk Level

Severity: medium

Estimated time to failure: unknown

Confidence: needs more data

Recommended Action

Inspect mechanical and electrical subsystems before continuing high-load operation.

LLM Maintenance Reasoning

LLM enabled: False

Summary:

Deterministic analysis found mixed behavior with medium risk.

Comparison to previous reports:

Previous reports available for comparison.

Engineer alert decision:

True - Severity is medium.

Missing context questions:

- Can the engineer confirm whether vibration, current, or temperature changed first?

LLM recommended next steps:

- Inspect mechanical and electrical subsystems before continuing high-load operation.

Recent Event Timeline