All System Diagnostic Report

The Report is created by Ediag

Vehicle Information

SN:9TBC29728913
Make:BMW/Rolls Royce/Mini
Model:528i
Year:1997.07
VIN:WBADD6100VBR32540
Mileage:281446 Miles
Test Time:09/24/2026 13:49:50

Inspection Result

TCM-Transmission Control Module - EGS 1 problems exist

1.29 Wheel Speed,Rear Right

ABS-Anti-Lock Braking System - DSC 2 problems exist

1.05 Wheel Speed,Rear Right,Not Plausible

2.21 Wheel-Speed-Sensor Wire,Front Left,Faulty

IC-Instrument Cluster - INSTR 2 problems exist

1.C7 Tank Sensor 1 (Fuel Pump Side)

2.D7 Tank Sensor 2 (Without Fuel Pump)

SRS-Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM 1 problems

1.18 Passenger Seat Occupancy Detector

LSZ/LCM-Light Switching Center 4 problems exist

1.16 Vertical Headlight Control Potentiometer, Wire Open

2.1F Control Of Q21/Q22 HVA

3.20 Control Of Q11/Q12 HVA

4.28 Thermal Sensor For Oillevel Defect

The following systems are OK:

1.ECM-Engine Control Module - DME/DDE

2.EWS-Elec. Immobilize System

3.RAD-Radio

4.ZKE-Central Body Electronic

5.A/C-Air Conditioning - IHKA

6.MFL-Multi-Function Steering Wheel
7.MID-Multi Information Display