

Invoice No :2510 **Service Labour Invoice** **Invoice Date**:27/03/2026 17:56

Mohali Auto hub 492, Mauli Road Sohana - 140308 Ph:8146131080 GST IN No.:03CNMPG7487A1Z1 BillType :Cash JC No. :6782 KMs :22444 RegnNo. :HP85 1439	CHANDAN KUMAR V P O SHILLAI TEHSIL SHILLAI MOHALI,MOHALI - 160055 Mob: 6376022023 JobType :Accident Repair FrameNo. :MD626AK36L2K27571 Model :NTORQ 125 DISC – RACE EDITION BSVI	NxtDue :PAID SERVICE NxtDueDt :25/07/2026 Mechanic :RAJ KUMAR
--	--	---

Item No	Particulars	Qty	Rate	Disc	Taxable	HSN	SGST	Rate CGST	Rate	MRP
K2150130	DAMPER HANDLE BAR	1.00	94.92	0.00	94.92	87149990	9.00	8.54 9.00	8.54	112.00
K2150210	CONTROL LEVER ASSY R	1.00	227.12	0.00	227.12	87141090	9.00	20.44 9.00	20.44	268.00
K2221400	SIDE TRIM FLOOR R TAPESET	1.00	268.64	0.00	268.64	87141090	9.00	24.18 9.00	24.18	317.00
KL2200208F	COVER HANDLE FRONT RACING RED + TAPESET	1.00	800.85	0.00	800.85	87141090	9.00	72.08 9.00	72.08	945.00
KL2200405D	PANEL FRONT MATTE BLACK + TAPESET	1.00	1344.92	0.00	1344.92	87141090	9.00	121.04 9.00	121.04	1587.00
KL2200808DA	PANEL BOT R TITANIUM GREY + TAPESET	1.00	962.71	0.00	962.71	87141090	9.00	86.64 9.00	86.64	1136.00
KL2202805D	SIDE PANEL R MATTE BLACK + TAPESET	1.00	1821.19	0.00	1821.19	87141090	9.00	163.91 9.00	163.91	2149.00
KL220490	MIRROR ASSY RH	1.00	248.31	0.00	248.31	70091090	9.00	22.35 9.00	22.35	293.00
AT02	ACCIDENT JOB - MC	1.00	1177.00	0.00	1177.00	9987	9.00	105.93 9.00	105.93	1388.86
	Parts Total	8.00		0.00	5768.66			519.18	519.18	
	Labour Total	1.00		0.00	1177.00			105.93	105.93	
	Sub Total	9.00		0.00	6945.66			625.11	625.11	

Grand Total	8195.88
Round Off	0.12
-----	-----
Net Total	8196.00

(Rupees Eight Thousand One Hundred and Ninety Six Only)

Item No	Description	Part Issued	Is Kit	Reason	Remarks
K2320600	KIT TWELVE K SERVICE NTORQ BS6	No	Yes		
(or)					
K6011090	SPARK PLUG BS4	No	No		

Note: Periodic Maintenance Parts are critical to the performance & health of your vehicle. Timely check & replacement, when not done would have a lasting impact on the overall drive experience & performance. As you have denied to replace PMP parts against recommended due interval, the dealership would not be responsible towards the decline in the vehicle performance in future.

For Mohali Auto hub

Authorised Signatory

Dear Customer, you haven't changed the oil (TR600410 / TR600640) as recommended, which may affect your vehicle's performance. To keep your vehicle running smoothly, please replace the oil as advised

Download TVS Connect App to book a service, Check Service History, Get Mileage & riding improvement tips, Contact road side assistance and much more



Scan for android Version



Scan for IOS Version