
Lecture 4
Polymer Crystallinity

Example: Spherulites

See Figures 2.4 and 2.8 in McCrum, N.G. "Principles of polymer engineering"

New York: Oxford University Press, 1997



after Arthur Tobolsky, Properties and structure of polymers (Wiley, 1960)

Glass Transitions

See graphs of glass transition temperature in Bicerano, Josef. *Prediction of Polymer Properties.*

New York: Marcel Dekker, 2002