**Ex.No.-1.1-Design and Draft the given 2D Sketches in modelling software.**

**AIM**


To sketch the given drawing with dimensions using fusion 360 tool.

**REQUIREMENTS:**


1. Autodesk fusion 360
2. Windows 10
3. 16 GB of RAM (integrated graphics recommend 2 GB or more)
4. 2.5 Mbps or faster download; 500 Kbps or faster upload

**PROCEDURE:**


1. Open Fusion 360 and click Create Sketch. Select the Right plane to start drawing. Select circle option and then proceed.





2. **Top Circle:** Draw a circle (diameter 20) straight up from the center point, about 65 mm away. Put another circle (diameter 32) around it.
3. **Bottom Circles:** Draw the bottom-middle and side circles (diameter 20 for the outer parts, diameter 10 for the inner holes) using the measurements shown in the drawing (like 47 mm across and 24 mm up).




4. **Center Part:** Draw a circle (diameter 40) right in the middle with the small inner curves (radius 6).





5. Draw the curved sides connecting everything (using radius 64, 20, and 10 arcs).
6. Click on **Modify** at the top, choose **Trim**, and click on all the extra lines crossing through your shape so you end up with one clean outline as per the sketch.





7. Double-check your dimensions against the blueprint.
8. Once your shape is fully closed and turns light blue, click **Finish Sketch**.





9. After finishing the sketch switch to drawing mode to plot the sketch in ISO standard.








10. Go to the Solid tab at the top.
11. Click Extrude, select your newly made sketch shape, type 20 mm for the distance.





**SKETCHS:**






**OUTPUT**




**RESULT**

**Thus, the given sketch is drawn and drafted using fusion 360 tool.**