REPAIR REPORT (sample)

CR001 / 2026-10-15

Work: hoist motor brake lining replacement

Symptom: delayed stop when lowering a load

Cause: worn brake lining

Action: replaced lining, adjusted gap

Downtime: 4 hours

(This is a sample file.)