

### MANUALS

| Issued by                 | Document                                                                                                                                             | Vrs.              | Date of Issue           | Current Revision                                                                                  |
|---------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-------------------------|---------------------------------------------------------------------------------------------------|
| PD-PS<br>„PZL<br>Bielsko” | Flight Manual<br>(acc. to. JAR-22)                                                                                                                   | PL, EN            | Issue I,<br>May 1994    | Rev. 0                                                                                            |
|                           | Flight Manual                                                                                                                                        | EN                | Issue III,<br>Dec. 1985 | Rev. 2, Sep. 14, 1992                                                                             |
|                           | Instrukcja U_ytkowania w Locie                                                                                                                       | PL                | Issue III,<br>Dec. 1985 | Rev. 2, Oct. 2, 1992                                                                              |
|                           | Instrukcja U_ytkowania w Locie<br>up to S/N B-1613<br>(if BE-30/50-3/86 <i>has not been</i><br><i>introduced - gliders without fifth seat belt</i> ) | PL                | Issue II,<br>Sep. 1980  | Rev. 31, Jul. 29, 1992                                                                            |
|                           | Flight Manual<br>from S/N B-1613 and up<br>(gliders approved for inverted flight)                                                                    | EN                | Issue II,<br>Sep. 1980  | Rev. 23, Jul. 29, 1992                                                                            |
|                           | Instrukcja Obsługi Technicznej<br>z harmonogramem prac okresowych                                                                                    | PL                | Issue III,<br>Sep. 1980 | Rev. 56, May 5, 2022                                                                              |
|                           | Technical Service Manual<br>with the Schedule of Maintenance Works                                                                                   | ENG               | Issue III               | Rev. 10, May 5, 2022                                                                              |
|                           | Technical Service Manual<br>of „Puchacz” SZD-50-3 Glider<br>(acc. to. JAR-22)                                                                        | PL, EN            | Issue I,<br>Nov. 1994   | Rev. 3, Dec. 12, 2006<br>(obligatory for SZD-50-3<br>equipped with hydraulic<br>wheel brake only) |
|                           | Technical Service Manual<br>of „Puchacz” SZD-50-3 Glider<br>(acc. to. JAR-22)                                                                        | PL, EN            | Issue I,<br>Nov. 1994   | Rev. 2, Aug. 2006                                                                                 |
|                           | Instrukcja Napraw                                                                                                                                    | PL                | Issue I,<br>1979        | Rev. 13, Jun. 3, 1981                                                                             |
|                           | Repair Manual                                                                                                                                        | EN                | Issue I,<br>1979        | Rev. 13, Jun. 3, 1981                                                                             |
|                           | Spare Parts Catalogue                                                                                                                                | PL, EN,<br>DE, RU | Issue 1982              |                                                                                                   |

### SERVICE BULLETINS

| SB No.        | Vrs.      | S/N                                              | Subject                                                | Compliance                           | Notes |
|---------------|-----------|--------------------------------------------------|--------------------------------------------------------|--------------------------------------|-------|
| BE-01/79      | PL        | From S/N B-903 to B-907                          | Changes into TSM                                       | Obligatory                           |       |
| BE-02/50-3/79 | PL,<br>EN | From S/N B-903 to B-907<br>& B-954, B-955, B-956 | Temporary flight limitations                           | Immediately after<br>receiving of SB |       |
| BE-01/50-3/80 | PL        | From S/N B-903 to B-<br>907, from B-954 to B-966 | Design changes, “spin”                                 | Successively                         |       |
| BE-02/50-3/80 | PL,<br>EN | From S/N B-903 to B-<br>907, from B-954 to B-966 | Roller in the towing-hook<br>control system introduced | Obligatory                           |       |
| BE-03/50-3/80 | PL,<br>EN | From S/N B-903 to B-<br>907, from B-954 to B-966 | Changes into FM                                        | Obligatory                           |       |
| BE-01/50-3/81 | PL,<br>EN | All S/N                                          | Changes into RM                                        | Obligatory                           |       |
| BE-02/50-3/81 | PL        | All S/N                                          | Changes into TSM, issue III<br>& IV                    | Obligatory                           |       |
| BE-03/50-3/81 | PL,<br>EN | All S/N                                          | Changes into FM                                        | Obligatory                           |       |

| SB No.        | Vrs.       | S/N                                                                              | Subject                                                                                                             | Compliance                        | Notes                  |
|---------------|------------|----------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|-----------------------------------|------------------------|
| BK-04/50-3/81 | PL, EN     | Up to S/N B-1079                                                                 | Changes in installation of TA-03-A oxygen equipment                                                                 | Obligatory                        |                        |
| BE-05/50-3/81 | PL, EN     | All S/N                                                                          | Changes into RM                                                                                                     | Obligatory                        |                        |
| BK-06/50-3/81 | PL, EN     | Up to S/N B-966                                                                  | Changes in rudder lower hinge                                                                                       | Immediately after receiving of SB |                        |
| BE-07/50-3/81 | PL, EN     | Only for gliders with landing gear fairing                                       | Changes into TSM                                                                                                    | Obligatory                        |                        |
| BE-08/50-3/82 | PL, EN     | All S/N except X-129                                                             | Changes into TSM, issue III & IV                                                                                    | Obligatory                        |                        |
| BK-09/50-3/82 | DE         | DE S/N B-955 & B-956                                                             | Changes required by LBA                                                                                             | Obligatory                        | Issued for LBA         |
| BK-10/50-3/83 | PL, EN, DE | From S/N B-903 to B-1084                                                         | Incorporation of cover on the aileron control angular lever in the front cockpit                                    | Obligatory                        |                        |
| BE-11/50-3/83 | PL, EN     | Gliders specified in item 2 of SB                                                | Changes into TSM & FM                                                                                               | Obligatory                        |                        |
| BE-12/50-3/83 | PL, EN     | All S/N up to do S/N B-1092                                                      | Inspection of hole in rudder torsion box near upper hinge                                                           | Obligatory                        |                        |
| BE-13/50-3/83 | DE         | All gliders in DDR                                                               | Changes into TSM & FM                                                                                               | Obligatory                        | Elaborated for GST DDR |
| BE-14/50-3/83 | PL, EN     | From S/N B-903 to B-1337                                                         | Inspection of and changes in pneumatic installation of instr. Panel in II cockpit                                   | Obligatory                        |                        |
| BE-15/50-3/83 | PL, EN     | All S/N                                                                          | Changes into TSM, issue III & IV                                                                                    | Obligatory                        |                        |
| BE-16/50-3/83 | PL, EN     | Up to S/N B-1081                                                                 | Inspection of correct coupling of drive lever with drive ends of elevator                                           | Obligatory                        |                        |
| BE-17/50-3/83 | PL, EN     | Up to S/N B-1334                                                                 | Inspection of composition excesses on the spar and wing lower covering                                              | Obligatory                        |                        |
| BE-18/50-3/83 | PL, EN     | As specified into it. 2 of SB                                                    | Changes into TSM, issue III & IV                                                                                    | Obligatory                        |                        |
| BE-19/50-3/84 | PL, EN     | From S/N B-903 to B-907, from B-954 to B-984, from B-1075 to B-1094, from B-1325 | Extension of maximum value of allowed glider all-up mass to 570 kg                                                  | Obligatory                        |                        |
| BE-20/50-3/84 | PL, EN     | From S/N B-1385                                                                  | Reduction of maximum empty glider mass with standard equipment to 370 kg                                            | Obligatory                        |                        |
| BK-21/50-3/84 | PL, EN     | All S/N up to do S/N B-1328                                                      | Securing of wheel brake control tension member against shifting off out of its fitting in form of the end with ball | Obligatory                        |                        |
| BK-22/50-3/84 | PL, EN     | Up to S/N B-1384                                                                 | Elimination of plays of the plugs /special screws/, fastening the canopy locks                                      | Obligatory                        |                        |

| SB No.               | Vrs.      | S/N                                                                                                                                                                 | Subject                                                                                                                                                                                                                                   | Compliance                 | Notes |
|----------------------|-----------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|-------|
| <b>BK-23/50-3/84</b> | PL,<br>EN | From S/N B-1404,<br>except B-1392                                                                                                                                   | Assembling of additional<br>buffer on trimming tab<br>control push-rod aimed<br>to limit the maximum "down"<br>deflection of the a.m.<br>trimming-tab                                                                                     | Obligatory                 |       |
| <b>BK-24/50-3/84</b> | PL,<br>EN | Up to S/N B-1404 except<br>B-1392                                                                                                                                   | 1. Enlarging the pass-by<br>hole for elevator control<br>push-rod on the front main<br>frame;<br>2. Revisions into TSM with<br>the Schedule of Periodic<br>Works (assembling and<br>disassembling of main<br>undercarriage)               | Obligatory                 |       |
| <b>BK-25/50-3/84</b> | PL,<br>EN | S/N X-127, X-129 &<br>From B-903 to B-907,<br>from B-1080 to B- 1094,<br>from B-1325 to B-1344,<br>from B-1385 to B-1404,<br>from B-1465 to B-1484<br>except B-1403 | The "lugs" welded to the<br>canopy frame cross rod /in<br>which the pin of emergency<br>jettisoning of the cable for<br>canopy holding in opened<br>position is fixed/ replaced<br>with the special fitting, fixed<br>to the canopy frame | Obligatory                 |       |
| <b>BE-26/50-3/84</b> | PL,<br>EN | From S/N B-903 to<br>B-1484                                                                                                                                         | Revision of allowed play in<br>stabilizer fittings                                                                                                                                                                                        | Obligatory                 |       |
| <b>BI-27/50-3/84</b> | PL        | As specified into SB                                                                                                                                                | Index of SB                                                                                                                                                                                                                               | Information                |       |
| <b>BE-28/50-3/86</b> | PL,<br>EN | All S/N up to S/N B-1613                                                                                                                                            | New edition of FM, issue III                                                                                                                                                                                                              |                            |       |
| <b>BE-29/50-3/86</b> | PL,<br>EN | All S/N up to S/N B-1613                                                                                                                                            | Revisions into TSM issue III<br>& IV                                                                                                                                                                                                      | Obligatory                 |       |
| <b>BE-30/50-3/86</b> | PL,<br>EN | All S/N up to S/N B-1613                                                                                                                                            | Allowance for inverted flight<br>and extended aerobatic<br>manoeuvres range                                                                                                                                                               | Acc. to User's<br>decision |       |
| <b>BE-31/50-3/86</b> | PL,<br>EN | All S/N up to S/N B-1613                                                                                                                                            | Changes into TSM                                                                                                                                                                                                                          | Obligatory                 |       |
| <b>BK-32/50-3/86</b> | PL,<br>EN | S/N X-127, X-129 from<br>B-903 to B-907, from<br>B-954 to B-984 except<br>B-971, B-974, B-977,<br>B-979                                                             | Replacement of screw<br>joining the wheel hube halves<br>of main undercarriage /dural<br>screws replaced with the<br>steel ones/                                                                                                          | Obligatory                 |       |
| <b>BK-33/50-3/87</b> | PL,<br>EN | S/N X-127, X-129, from<br>B-903 to B-1613                                                                                                                           | Securing of bolt joining the<br>spars to avoid the possibility<br>of disengage the connection                                                                                                                                             | Obligatory                 |       |
| <b>BE-34/50-3/87</b> | PL,<br>EN | S/N X-129 and latest S/N                                                                                                                                            | Extension of life time up to 6<br>000 FH                                                                                                                                                                                                  | Obligatory                 |       |
| <b>BE-35/50-3/87</b> | PL,<br>EN | S/N B-1606, B-1609 up<br>to B-1613, from B-1617<br>to B-1620                                                                                                        | Changes into TSM, issue III<br>& IV and FM, issue<br>II/IX.1980 & III/XII.1985                                                                                                                                                            | Obligatory                 |       |
| <b>BI-36/50-3/87</b> | PL        |                                                                                                                                                                     | Index of SB                                                                                                                                                                                                                               | Information                |       |
| <b>BE-37/50-3/89</b> | PL,<br>EN | The gliders adopted for<br>aerobatics acc. BE-30/85<br>& gliders from S/N<br>BE-1617 up                                                                             | The distinc designation of<br>Puchacz approved for<br>extended aerobatic<br>manoeuvres                                                                                                                                                    | Obligatory                 |       |

| SB No.                           | Vrs.      | S/N                                                    | Subject                                                                                                                                                              | Compliance                                                                                                                                                          | Notes             |
|----------------------------------|-----------|--------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| <b>BE-38/50-3/89</b>             | PL,<br>EN | S/N X-127, X-129 & up to B-1973                        | Securing of pulley T50 in trimming-tab control system against the ev. Shifting – off out of the bearing                                                              | Obligatory, accomplished up to Apr. 31, 1990                                                                                                                        |                   |
| <b>BR-39/50-3/89</b>             | PL,<br>EN | S/N X-127, X-129 & from B-903 to B-1482                | Plugging of the lightening hole in the upper hinge of the rudder                                                                                                     | If no other damages exist the change should be introduced when the flights are broken                                                                               |                   |
| <b>BR-40/50-3/90</b>             | PL,<br>EN | S/N X-127, X-129 & from B-903 to B-1553                | Replacement of the pin in the securing pivot of the tailplane in assembled condition                                                                                 | In case the pin is damaged, the change shall be introduced immediately. If no damages exist the change is to be introduced during the 1 000 FH inspection or repair |                   |
| <b>BI-41/50-3/90</b>             | PL        | As specified into SB                                   | Index of SB                                                                                                                                                          | Information                                                                                                                                                         |                   |
| <b>BE-42/50-3/92</b>             | PL,<br>EN | All S/N up to B-2052                                   | Elimination of the possibility that the closing cable of the rudder control system can jam onto the transceiver connector fixed on the frame set near the front seat | Obligatory                                                                                                                                                          |                   |
| <b>BR-43/50-3/92</b>             | PL,<br>EN | Acc.to the "List of....."                              | The case of "sinking" of the trimming-tab control system torque tube into the oval opening in the fin                                                                | When checked that the "sinking" is possible, introduce by nearest occasion                                                                                          |                   |
| <b>BE-45/50-3/92</b>             | PL,<br>EN | All S/N up to B-2054                                   | Checking of max. permissible load mass taking into account the permissible fuselage with tailplane, mass min. permissible wing mass and empty glider mass            | Obligatory after repairs                                                                                                                                            |                   |
| <b>BE-46/50-3/92</b>             | PL,<br>EN | All S/N                                                | Changes into TSM, tail wheel, main bolt with securing lock                                                                                                           | Obligatory                                                                                                                                                          |                   |
| <b>A-047/50-3/94</b>             | PL,<br>EN | All S/N up to B-2056 and latest up to B-2056           | The case of loosening the screw fastening the distance sleeve on which the air brake plate arm rotates                                                               | Obligatory                                                                                                                                                          |                   |
| <b>BE-048/<br/>SZD-50-3/2000</b> | PL,<br>EN | All S/N                                                | Inspection of fuselage front bracket console                                                                                                                         | Obligatory                                                                                                                                                          | AD SP-0059-2000-A |
| <b>BE-049/<br/>SZD-50-3-2000</b> | PL,<br>EN | All S/N - damaged                                      | Replacement of fuselage front fitting                                                                                                                                | Obligatory                                                                                                                                                          | AD SP-0094-2000-A |
| <b>BE-050/<br/>SZD-50-3/2002</b> | PL,<br>EN | From B-903 to B-907, from B-954 to B-963, B-965, B-966 | Verification of control stick length                                                                                                                                 | Obligatory                                                                                                                                                          |                   |
| <b>BE-051/<br/>SZD-50-3/2003</b> | PL,<br>EN | All S/N                                                | Service life extension to 6 750 FH                                                                                                                                   | After 6 000 FH                                                                                                                                                      |                   |
| <b>BE-052/<br/>SZD-50-3-2003</b> | PL,<br>EN | All S/N                                                | Inspection of torque tube in air brake control system                                                                                                                | Obligatory                                                                                                                                                          | AD SP-0052-2003-A |
| <b>BE-053/<br/>SZD-50-3/2003</b> | PL,<br>EN | S/N B-1984 & B-1988                                    | Service life time extension from S/N B-1984 & B-1988 up to 12 000 FH and revisions to TSM                                                                            | Obligatory                                                                                                                                                          |                   |

| SB No.                           | Vrs.      | S/N                                                                                           | Subject                                                                                                                                           | Compliance                                            | Notes                                  |
|----------------------------------|-----------|-----------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|----------------------------------------|
| <b>BE-054/<br/>SZD-50-3/2003</b> | PL,<br>EN | All S/N                                                                                       | Inspection of turnbuckle in the rudder control system                                                                                             | Obligatory                                            | AD SP-0012-2004-A                      |
| <b>BE-055/<br/>SZD-50-3/2004</b> | PL,<br>EN | All S/N except S/N B-1990                                                                     | Inspection of control stick                                                                                                                       | Obligatory                                            | EASA AD 2004-0003                      |
| <b>BE-056/<br/>SZD-50-3/2004</b> | PL,<br>EN | S/N B-1990                                                                                    | Service life time extension up to 12 000 FH and revisions to TSM                                                                                  | Obligatory                                            |                                        |
| <b>BE-057/<br/>SZD-50-3/2006</b> | PL,<br>EN | All S/N                                                                                       | Introduction of an extra pull rod segment in the ruder control system                                                                             | Obligatory                                            | EASA AD 2006-0317                      |
| <b>BE-058/<br/>SZD-50-3/2006</b> | PL,<br>EN | All S/N                                                                                       | Inspection of the rudder bottom hinge and revision to TSM                                                                                         | Obligatory                                            | EASA EAD 2006-0243-E                   |
| <b>BE-059/<br/>SZD-50-3/2007</b> | PL,<br>EN | All S/N up to B-2207 & 503199327, 503A04001, 503A05002, 503A05003                             | Inspection of the intermediate lever bolt in airbrake control system in the wing                                                                  | After receiving of SB                                 | EASA AD 2007-0275-E                    |
| <b>BE-060/<br/>SZD-50-3/2007</b> | PL,<br>EN | S/N B-2024                                                                                    | Service life time extension for S/N B-2024 up to 12 000 FH and revisions to TSM                                                                   | After receiving of SB                                 | EASA.A.C.07 360                        |
| <b>BE-061/<br/>SZD-50-3/2009</b> | PL,<br>EN | S/N B-2043                                                                                    | Service life time extension to B-2 043 up to 12 000 FH and revisions to TSM                                                                       | After receiving of SB                                 | EASA 10028802                          |
| <b>SIL-001/SZD/2012</b>          | PL,<br>EN | All SZD Allstar gliders                                                                       | Clarification of BE-043/92 „Jantar”                                                                                                               | According to User's decision                          |                                        |
| <b>SIL-002/SZD/2012</b>          | PL,<br>EN | SZD-48-3 „Jantar Std. 3”, SZD-50-3 „Puchacz” (OSTIV'76 vrs. & acc. to JAR-22), SZD-59 „Acro”. | Terms of use and further maintenance of the aircraft instruments different than „PZL-WARSZAWA II”, which have been applied so far for SZD gliders | In case of assembling into instrument panel (panels). |                                        |
| <b>SIL-001/SZD/2013</b>          | PL,<br>EN | SZD-50-3 „Puchacz”, gliders with replaced fuselage front fittings                             | Fuselage front fitting – requirements of BE-049/SZD-503-2000                                                                                      | According to User's decision                          |                                        |
| <b>BE-062/<br/>SZD-50-3/2013</b> | PL,<br>EN | All S/N                                                                                       | Inspection of torque tube in air-brake control system                                                                                             | After receiving of SB                                 | EASA AD 2014-0015<br>FAA AD 2014-12-08 |
| <b>BE-063/<br/>SZD-50-3/2014</b> | PL,<br>EN | All S/N, SZD-50-1-M (X-127), SZD-50-2 (X-129)                                                 | Inspection of rudder cable fitting blocks                                                                                                         | After receiving of SB                                 | FAA AD 2015-13-03                      |
| <b>BE-064/50-3/2022</b>          | PL,<br>EN | All S/N, except S/N B-1984, B-1988, B-1990, B-2024, B-2043                                    | Service life time extension up to 12 000 FH and revisions to TSM                                                                                  | According to User's decision                          |                                        |

PL – Polish, EN – English, DE – German

**END OF RECORD**