

MANUALS

Issued by	Document	Vrs.	Date of Issue	Current Revision
Allstar PZL Glider"	Flight Manual Doc. No. 542.4.01	EN, PL	Issue II, April 2014	Rev. 2, May 2017
	Technical Service Manual Doc. No. 542.4.02	EN, PL	Issue II, April 2014	Rev. 2, May 2017

SERVICE BULLETINS

SB No.	Vrs.	S/N	Subject	Compliance	Notes
BE-001/ 54-2/2018	PL EN	542.A.11.002; 542.A.14.003; 542.A.14.004; 542.A.14.005; 542.A.14.006; 542.A.15.007; 542.A.15.008; 542.A.15.009; 542.A.15.010; 542.A.15.011; 542.A.16.012; 542.A.16.013; 542.A.16.014; 542.A.16.015	Additional securing of bushing on the wing's fittings as well as fitting of horizontal stabilizer	After receiving of SB	EASA AD 2019-0077
BE-002/ 54-2/2017	PL EN	542.A.11.002; 542.A.14.003; 542.A.14.004; 542.A.14.005; 542.A.14.006; 542.A.15.007; 542.A.15.008; 542.A.15.009; 542.A.15.010; 542.A.15.011; 542.A.16.012; 542.A.16.013; 542.A.16.014; 542.A.16.015; 542.A.17.016W	1. Increasing of MTOM for U & A vrs., stall warning device cancelled as obligatory equipment 2. Modification of elevator drive in cockpit	Dependable on the action: 1. after receiving of SB 2. at the nearest scheduled inspection	
BE-004/ 54-2/2026	PL EN	All sailplanes of the SZD-54 "Perkoz" type, model SZD-54- 2 "Perkoz"	1. Inspection of the airbrake driving torsional tube 2. Procedure to follow if damage to the torsional tube is detected	Upon receipt of this Service Bulletin	EASA AD 2026-0086
BE-004/ 54-2/2026 Revision 1	PL EN	All sailplanes of the SZD-54 "Perkoz" type, model SZD-54- 2 "Perkoz" up to and including serial number 542.A.25.049	1. Inspection of the airbrake driving torsional tube 2. Procedure to follow if damage to the torsional tube is detected	Upon receipt of this Service Bulletin	EASA AD 2026-0086
SIL-003 /SZD/2018	PL EN	All SZD-54-2 Sailplanes up to 542.A.18.021W	Connections at elevator's drive	Before next flight	EASA AD 2018-0237-E
SIL-004 /SZD/2019	EN	All S/N up to 542.A.18.024	Wing tips locking system	Before next flight	

PL – Polish, EN – English

END OF RECORD