

Measured arm phase and base yaw locate the sensor

$$x_s = x_b + d[\cos(\psi + \phi), \sin(\psi + \phi)]$$

Illustrative pose and angle; no source location is used.

