


## **Task Scheduler**



## **Button State Machine**



## **Heater State Machine**



## **Output to Server**

Always Outputs over Uart Every 1000 ms

DISPLAY( snprintf(output, 64, "<%02d, %02d, %d, %04d>\n\r", temperature, set\_point, heater\_on, seconds\_since\_restart)); seconds\_since\_restart += 1;

// adding plus 1 after because on boot a message is initially sent // It doesn't wait a second because all tasks initially fire