

Customer Service Report



HEINLEIN FOODS USA
1215 SW 4TH AVE
DELRAY BEACH, Florida, 33444-2276
Account Number: 0508275714



ECOLAB SERVICE REPRESENTATIVE
Olivia Sparkman
olivia.sparkman@ecolab.com

www.ecolab.com [Global Locations Listing](#)

Service Summary



Service Date(s) 22-Jan-25 **Hours of Service** 4.0



Service Visit Type Technical Visit



Reviewed With Javier Sotolongo
Sanitation Manager



Summary
Scheduled monthly service visit to the plant to monitor the cleaning process, concentration of cleaning chemistry, safety observations, and meet with the sanitation team.

ECOLAB®

Service Activity

Account Name: HEINLEIN FOODS USA

Date: January 22, 2025



Service Type Business Review



Service Technician Activity Entry / Exit / Site Meeting



Actual Duration 0 minutes



Reviewed With Javier Sotolongo



Description

- New Lafferty wall-mounted foamers have been added to both 1205 and 1215 production rooms. The new wall-mounted foamers are supporting sanitation team with proper foam coverage with the proper foam texture.
- 1205 production room is now in operation with new enrobers and chillers on the production line. 1215 production room is down for rebuild. The room has undergone renovations for the floor and production line.
- No reports of micro or quality concerns were reported to Ecolab at the time of the service visit.

ECOLAB®

Service Activity

Account Name: HEINLEIN FOODS USA

Date: January 22, 2025

Customer Service Report



HEINLEIN FOODS USA

1215 SW 4TH AVE
DELRAY BEACH, Florida, 33444-2276
Account Number: 0508275714



ECOLAB SERVICE REPRESENTATIVE

Olivia Sparkman
olivia.sparkman@ecolab.com

www.ecolab.com

[Global Locations Listing](#)



Service Type

Food Safety and Quality



Service Technician Activity

Site Audit



Actual Duration

0 minutes



Reviewed With

Javier Sotolongo



Description

1205:

- New Lafferty wall-mounted foamer was in good condition with all components still working and operable.
- Floors in good condition with no cracks or holes.
- Boots in the gowning room were clean and were not covered in food debris. It is recommended to clean all footwear covered in food soils prior to entering and exiting the production room to decrease the risk of contamination.

1215:

- Room is not in production and is currently closed.
- Floors in 1215 have been repaired and restored to slope towards the drain. There are no longer any cracks or holes in the floor that may be harborage sites for bacteria and food soil.
- Packaging equipment is located above the drain in this room. It is recommended to move the packaging equipment to prevent water damage in the equipment. Moving the packing machine will also allow for greater access to clean the drains during the sanitation process.



Service Activity

Account Name: HEINLEIN FOODS
USA

Date:
January 22, 2025



Service Type

Plant Safety



Service Technician Activity

Safety Observation /
Recommendation



Actual Duration

0 minutes



Reviewed With

Javier Sotolongo



Description

- Sanitation team was not wearing proper eye wear (goggles) during the cleaning and sanitation process. It is recommended to wear eye protection because in an open plant layout, there is a higher risk of being sprayed with water or chemical solution. Eye protection is listed as proper PPE on the safety data sheets and labels for all chemistry being used at Heinlein Foods.
- Waterproof clothing/rain gear were worn while handling chemical. It is recommended to also wear chemical resistant gloves while cleaning and sanitizing as an additional layer of protection from chemical. It is also recommended for employees to wear non-slip, steel-toe boots while in the plant to protect feet from chemical, slips, and falling objects.
- All secondary chemical containers and chemical equipment were properly labelled with the chemistry they contained.

Customer Service Report



HEINLEIN FOODS USA
1215 SW 4TH AVE
DELRAY BEACH, Florida, 33444-2276
Account Number: 0508275714



ECOLAB SERVICE REPRESENTATIVE
Olivia Sparkman
olivia.sparkman@ecolab.com

www.ecolab.com [Global Locations Listing](#)

Service Activity

Account Name: HEINLEIN FOODS
USA

Date:
January 22, 2025

	Service Type	Cleaning & Performance Optimization		Service Technician Activity	Concentration Checks
	Actual Duration	0 minutes		Reviewed With	Javier Sotolongo

Description

Advantis SM FC: 22,170 ppm (6 drops #52)

- In recommended range of 15,600 - 39,100 ppm.

Quorum Clear V: 400 ppm (8 drops #43)

- In no rinse, food contact surface range of 200-400 ppm.

- Concentrations for foaming and sanitizing chemicals are in range for their purpose.
- No action needed at this time.
- It is recommended that Heinlein Foods tests the concentration of the chemical solutions being used in the 3-compartment sinks, foamer, and sanitizer using the supplied test kits once a week. Testing and documenting the concentrations of each chemistry on a frequent basis will help to monitor the chemical usage and identify areas of optimization.

Service Activity

Account Name: HEINLEIN FOODS
USA

Date:
January 22, 2025

	Service Type	Equipment & Engineering		Service Technician Activity	Equipment Maintenance
	Actual Duration	0 minutes		Reviewed With	Javier Sotolongo

Customer Service Report



HEINLEIN FOODS USA

1215 SW 4TH AVE

DELRAY BEACH, Florida, 33444-2276

Account Number: 0508275714



ECOLAB SERVICE REPRESENTATIVE

Olivia Sparkman

olivia.sparkman@ecolab.com

www.ecolab.com

[Global Locations Listing](#)



Description

- Lafferty foamers in 1215 and 1205 have been replaced. Foam texture being dispensed was the proper consistency. Both foamers were in good condition and working as designed.
- Water pressure and temperature in 1205 is not adequate to facilitate efficient and proper cleaning of soils. The temperature on the water heater was 140 degrees F but actual temperature was around 80 degrees F. The current temperature of the water is not hot enough to melt the chocolate soil leading to an increase in manual cleaning and difficulty pre-rinsing soils, especially on enrober conveyors. It is recommended to increase the water pressure and repair the water heater to provide the proper flow and temperature to remove chocolate soils.
- Due to the lack of pressure and temperature of the water for rinsing, hoses are being brought in from 1215 through the warehouse because there is better pressure and higher temperature water being dispensed. While this is increasing the efficiency of rinsing in 1205, it is not recommended to bring hoses from the other production rooms through the warehouse. Bringing hoses through the warehouse increases the risk of contamination because the same level of cleanliness is not practiced in the warehouse and production rooms. There is also a risk of bringing in peanut allergens into 1205 from the hoses on 1215 if the proper precautions of cleaning the hoses is not taken.
- Table legs and 3x1 racks have holes in the legs creating potential harborage sites. It is recommended to replace the tables with holes and install permanent L-brackets on the floor to hold up the pallets of ingredients.



Service Activity

Account Name: HEINLEIN FOODS
USA

Date:
January 22, 2025



Service Type

Cleaning & Performance
Optimization



Service Technician Activity

OPC / Environmental



Actual Duration

0 minutes



Reviewed With

Javier Sotolongo



Description

- Pre-cleaning was successful with visible debris removed from conveyors and enrobers. The top and underside of the equipment was scrubbed and rinsed.
- Application of foam was successful and completed in the recommended manner. Walls were foamed first followed by equipment. Undersides of the equipment were foamed. Foam application was from bottom to top as discussed in foam application training.
- It is recommended to let the foam sit for 5 - 10 minutes prior to scrubbing the foam. It was observed that scrubbing the foam would occur immediately after application. To allow the foam to work properly and to its fullest extent, it is recommended to let the Advantis SM FC foam sit on the soiled surface to penetrate any film build-up.
- Conveyors were running during the cleaning and sanitation process. It is recommended to continue this best practice to ensure all surfaces on the conveyor belts have the recommended chemical contact time before being rinsed. Sanitation employees are doing an excellent job of breaking down the equipment and cleaning individual pieces manually. Individual pieces are placed in a red bucket containing Advantis SM FC for cleaning.
- Color-coding program was being followed at the time of this service visit. Javier, sanitation manager, stated he is working with his team to ensure that the program was adhered to during the cleaning and sanitation process. Color-coding was also addressed in the training provided.

Customer Service Report



HEINLEIN FOODS USA

1215 SW 4TH AVE

DELRAY BEACH, Florida, 33444-2276

Account Number: 0508275714



ECOLAB SERVICE REPRESENTATIVE

Olivia Sparkman

olivia.sparkman@ecolab.com

www.ecolab.com

[Global Locations Listing](#)

- For packaging equipment, it is recommended to use a moist rag or alcohol wipes to clean the equipment. The equipment is being wiped with a moist rag on the top of the equipment but on the bottom near the electrical equipment, water was being used to rinse and clean. It is recommended to use a moist rag or wipe to clean the packaging equipment to minimize the moisture in the environment. Cleaning the equipment with a moist rag or alcohol, compared to washing with a hose, will increase the lifespan of the equipment because there is smaller risk for water to get into the equipment or rust.
- Hose nozzles are being laid on the floor when not in use. It is recommended keep all hose nozzles up and off the floor to reduce the risk of contamination. When the hose nozzles are on the floor, they risk picking up contaminants (bacteria, yeast, mold, or soil) from a non-food contact surface and spraying the contaminants on food contact surfaces.

Customer Signature

Ecolab Signature

Print Name/Sign-Off Date

Print Name/Sign-Off Date



At Ecolab, our goal is to partner with customers to help make their facilities cleaner, safer and healthier. We lead the industry at providing a unique combination of personalized service and customized cleaning and sanitizing solutions that enhance food safety, operational efficiency and cost savings – in the safest, most sustainable way.