



N015AV (S/N: W14031869022) — Physical Enclosure Damage Diagnostic Report

Immfly Ground Operations / IT — Session: September 1, 2026

Field	Value
Machine	N015AV (S/N: W14031869022)
Affected component	Unit enclosure/chassis — visible physical damage
Initial symptom	Visible physical damage to the unit's case
Root cause	Confirmed — physical damage to the enclosure, a hardware fault
Impact	Structural integrity of the unit is compromised; may affect the seating and protection of internal components (disk, modem, connectors) depending on damage severity and location
Recommended action	Physical inspection and enclosure replacement required

Narrative Summary

During physical inspection of N015AV, visible damage was found on the unit's case/enclosure. This is a confirmed physical hardware fault, distinct from the software/firmware-level issues documented elsewhere in the fleet (modem registration, SIM detection, or AP configuration problems). Enclosure damage is not something that can be diagnosed further or worked around at the software level.

Depending on the location and severity of the damage, a compromised enclosure can also affect the protection and secure seating of internal components (such as the disk, modem, or internal cabling), so a closer physical inspection is recommended to rule out any secondary damage beyond the case itself before returning the unit to service.

Conclusion and Recommendation

N015AV requires a physical enclosure repair or replacement. No further remote diagnostics are needed to confirm this fault, as the physical damage has already been visually confirmed.

Recommended action: Escalate for physical inspection and enclosure replacement, following the standard repair-order workflow used for other confirmed hardware faults in the fleet. As part of the repair, a full functional check (disk, modem/connectivity, WiFi, and display) is recommended to confirm no internal components were affected by the impact before returning the unit to service.