



N028AV (S/N: W14061878022) — Broken WiFi Antenna Diagnostic Report

Immfly Ground Operations / IT — Session: August 27, 2026

Field	Value
Machine	N028AV (S/N: W14061878022)
Affected component	WiFi antenna — physical damage
Initial symptom	WiFi antenna is physically broken
Root cause	Confirmed — physical damage to the WiFi antenna, a hardware fault
Impact	Degraded or absent WiFi coverage for passengers connecting to the onboard access point
Recommended action	Physical antenna replacement required

Narrative Summary

During physical inspection of N028AV, the unit's WiFi antenna was found to be physically broken. Unlike the software/firmware-level connectivity issues documented elsewhere in the fleet (modem registration failures, SIM detection problems, or AP configuration issues), this is a confirmed physical hardware fault: the antenna itself is damaged, which directly and unavoidably degrades or eliminates the radio-frequency performance of the onboard WiFi access point regardless of how correctly the software stack (hostapd, dnsmasq/DHCP, bridging) is configured.

A physically damaged antenna is not something that can be diagnosed further or worked around at the software level — no configuration change, service restart, or firmware update can restore signal performance lost to a broken antenna. This is a hardware fault requiring physical replacement of the affected part.

Conclusion and Recommendation

N028AV requires a physical WiFi antenna replacement before it can be expected to provide normal onboard WiFi coverage to passengers. No further remote diagnostics are needed to confirm this fault, as the physical damage has already been visually confirmed.

Recommended action: Escalate for physical antenna replacement, following the standard repair-order workflow used for other confirmed hardware faults in the fleet. Once the antenna is replaced, a quick WiFi functional check (SSID visibility and successful client association/DHCP, similar to the checks performed on other units in this fleet) is recommended to confirm the repair before returning the unit to service.