

MOTOR INSURANCE CLAIM FORM		OWN DAMAGE
Claim No.: DP-2026-001847	Type: DP — OWN DAMAGE	Insurer: Seguros Meridiano, S.A.

STATUS: PENDING REVIEW

1. POLICYHOLDER INFORMATION	
Full Name:	Carlos Enrique Mejía Reyes
ID / Cédula:	001-1234567-8
Date of Birth:	March 14, 1985
Address:	Calle El Conde 342, Apt. 5B, Santo Domingo, D.N.
Phone:	+1 (809) 445-2310
Email:	cmejia@email.com
Policy Number:	POL-SDQ-2024-098321
Policy Start:	January 1, 2025
Policy End:	December 31, 2025
Coverage Type:	Comprehensive (All-Risk)
Deductible:	DOP 15,000

2. INSURED VEHICLE	
Make / Model:	Toyota Corolla XEi
Year:	2022
Color:	Pearl White
License Plate:	A-456789
VIN / Chassis:	JTDBL40E099087432
Engine No.:	2ZR-1098234
Declared Value:	DOP 1,450,000
Odometer (at loss):	34,210 km

3. INCIDENT DETAILS	
Incident Date:	May 19, 2026
Incident Time:	07:42 AM
Location:	Av. 27 de Febrero, intersection with Av. Máximo Gómez, Santo Domingo
Road Condition:	Dry, clear visibility
Weather:	Sunny

Police Report No.:	PN-SDQ-2026-043217
Report Date:	May 19, 2026

4. INCIDENT NARRATIVE

The insured vehicle was stopped at a red light at the intersection of Av. 27 de Febrero and Av. Máximo Gómez when it was struck from behind by a 2018 Honda Civic (plate B-112233) driven by an unidentified male who subsequently fled the scene. The impact caused significant damage to the rear bumper, trunk lid, and exhaust assembly. The insured immediately called the National Police (Policía Nacional) and waited for officers to arrive and file the report. No injuries were sustained. The vehicle was towed to the insured's regular workshop, Taller Multimarca San Isidro.

5. DAMAGE ASSESSMENT

Part / Component	Damage Description	Est. Repair Cost (DOP)
Rear bumper assembly	Complete replacement required — cracked and detached	28,500
Trunk lid (boot)	Heavily dented, paint abraded — replacement required	45,000
Rear left tail light	Shattered — replacement	12,800
Rear right tail light	Cracked lens — replacement	12,800
Exhaust muffler	Displaced and bent — realignment + partial replacement	9,500
Rear tow hook cover	Lost on impact — replacement	2,200
Labor (body & paint)	Approx. 18 man-hours @ DOP 900/hr	16,200
TOTAL ESTIMATE		127,000

6. DOCUMENTS SUBMITTED

- Copy of vehicle registration (marbete) — current year
- Copy of policyholder national ID (cédula)
- Copy of driver's license (current)
- Police report No. PN-SDQ-2026-043217
- Workshop repair estimate — Taller Multimarca San Isidro
- 4 photographs of vehicle damage (rear section)
- Tow truck receipt — Grúas Rápidas SDQ

7. DECLARATION

I, Carlos Enrique Mejía Reyes, hereby declare that all information provided in this claim form is truthful and complete to the best of my knowledge. I understand that any misrepresentation may result in denial of the claim and termination of the insurance policy.

_____	_____	_____
Policyholder Signature	Date	Adjuster Signature

CONFIDENTIAL — For insurer use only. Claim DP-2026-001847 | Seguros Meridiano, S.A. | Av. Winston Churchill 1099, Santo Domingo, D.N.,
Dominican Republic | Tel: +1 (809) 555-7000 | claims@meridianosd.com