AMBER CALIBRATION

The amber instrument records a calibration measurement of 47 millimetres.

The operator verifies the instrument before recording the measurement.

The inspection record contains the instrument name and the measured value.

This calibration record applies to the amber instrument only.

The operator records the date and signs the completed inspection sheet.

The supervisor compares the recorded value with the reference block.

The recorded value is valid only after the reference block check is signed.

COBALT CALIBRATION

The cobalt instrument records a calibration measurement of 63 millimetres.

The operator checks the reference block before recording the measurement.

The inspection record contains the reference block and the measured value.

This calibration record applies to the cobalt instrument only.

The operator records the date and signs the completed inspection sheet.

The supervisor compares the recorded value with the reference block.

The recorded value is valid only after the reference block check is signed.