





Flat noise levels - Pentax, K-1 Mark II, 144000 ISO (ISO-144000) 2.5 red green blue ideal 2 standard deviation 1.5 0.5 0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 8.0 0.9 brightness













Flat noise levels - Pentax, K-1 Mark II, 204800 ISO (ISO-204800) 2.5 red green blue ideal 2 standard deviation 1.5 0.5 0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 8.0 0.9 brightness













Flat noise levels - Pentax, K-1 Mark II, 288000 ISO (ISO-288000) 2.5 red green blue ideal 2 standard deviation 1.5 0.5 0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 8.0 0.9

brightness













Flat noise levels - Pentax, K-1 Mark II, 409600 ISO (ISO-409600) 2.5 red green blue ideal 2 standard deviation 1.5 0.5 0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 8.0 0.9 brightness













Flat noise levels - Pentax, K-1 Mark II, 576000 ISO (ISO-576000) 2.5 red green blue ideal 2 standard deviation 1.5 0.5 0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 8.0 0.9

brightness









Flat noise levels - Pentax, K-1 Mark II, 819200 ISO (ISO-819200) 2.5 red green blue ideal 2 standard deviation 1.5 0.5 0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 8.0 0.9 brightness

