			0	, 0 ,		J (	<i>.</i>	
10000	1000	1j = 2.1016	2a=2.125	2j = 0.7168	3a=2.2578	3j = 0.752	4a=1.7109	4j = 0.7852
10000	100	1j = 15.1875	2a = 9.5	2i = 6.0469	3a=5.2031	3j = 3.0234	4a = 7.0	4j = 4.0469
10000	10	1j = 8.9531	2a = 4.9219	2j = 4.4844	3a = 8.7812	3j = 5.0156	4a = 6.8438	4j = 6.3438
10000	150	1i = 8.3438	2a = 8.0312	2j = 3.0391	3a=5.5469	3j = 3.6406	4a = 7.4688	4j = 3.7344
10000	1	1i = 12.6875	2a = 8.2188	2j = 5.6094	3a = 10.4062	3j = 2.9609	4a = 10.8438	4j = 2.3516
10000	500	1j = 12.0075 1j = 4.0469	2a = 3.8906	2j = 3.0034 2j = 2.0234	3a=1.7891	3j = 1.4883	4a=1.9609	4j = 1.1836
10000	50	1j = 13.4062	2a = 12.0938	2j = 3.8906	3a=6.6562	3j = 4.4531	4a = 7.6562	4j = 3.3594
10000	1000	1j = 13.4002 1j = 2.1641	2a=12.0330 2a=3.0703	2j = 0.9414	3a = 0.0002 3a = 1.7734	3i = 0.9336	4a = 1.8359	4j = 0.7852
1000	1000	1j = 2.1041 1j = 7.5938	2a = 5.2656	2j = 0.9414 2j = 2.5234	3a=1.7734 3a=5.9531	3j = 0.9330 3j = 2.1953	4a=1.8599 $4a=5.8594$	4j = 0.7632 4j = 2.5234
1000	100	1j = 7.9938 1j = 7.0938	2a = 4.2656	2j = 2.3234 2j = 3.1719	3a=4.2656	3j = 2.1933 3j = 2.9062	4a = 3.7031	4j = 2.5254 4j = 2.6953
1000	150	1j = 7.0938 1j = 5.7969	2a = 4.2050 2a = 7.1562	2j = 3.1719 2j = 2.3125	3a=4.2030 $3a=2.8203$	3j = 2.3002 3j = 2.4297	4a = 5.7031 $4a = 5.2344$	4j = 2.0933 4j = 2.0234
1000	1	1j = 5.7909 1j = 7.4531	2a = 4.6094	2j = 2.3123 2j = 3.2969	3a=2.0203 3a=4.25	3j = 2.4297 3j = 2.1016	4a = 3.2344 $4a = 4.0156$	4j = 2.0254 4j = 1.9141
1000	500			-		-	4a = 4.0150 $4a = 5.5469$	-
1000	500 50	1j = 4.8281 1j = 5.7656	2a=5.8594 2a=6.1406	2j = 2.5938	3a=4.2969 3a=5.1719	3j = 1.8047	4a = 3.2031	4j = 1.8828
1000	100		2a = 0.1400 2a = 15.0625	2j = 2.5234		3j = 2.4766	4a = 3.2031 $4a = 9.0312$	4j = 2.4141
		1j = 24.0625		2j = 5.2031	3a=9.8438	3j = 8.2188		4j = 8.5312
100	10	1j = 103.25	2a=59.25	2j = 19.5625	3a=40.375	3j = 23.0625	4a=21.9688	4j = 12.4062
100	$\frac{50}{10}$	1j = 19.9766	2a=12.1875	2j = 12.6875	3a=18.1875	3j = 14.4375	4a=62.25	4j = 8.5938
10		1j = 68.8125	2a=40.625	2j = 35.8125	3a=17.1875	3j = 46.375	4a = 28.375	4j = 24.625
10	1	1; _ 9 1707	2a=116.25	2j = 131.25	3a=334.25	3j = 30.375	40-9 9724	4; _ 1 1000
2000	1000	1j = 2.1797	2a=2.3672	2j = 0.8242	3a=2.4922	3j = 0.7852	4a=2.2734	4j = 1.1992
2000	10	1j = 4.2031	2a=4.3906	2j = 2.5547	3a=3.6719	3j = 2.2109	4a=2.9219	4j = 2.0234
2000	150	1j = 4.3906	2a=5.9766	2j = 1.6016	3a=3.0703	3j = 1.5352	4a=3.3906	4j = 1.3555
2000	1	1j = 4.4531	2a=5.2344	2j = 1.9297	3a=3.0234	3j = 1.8672	4a=3.7344	4j = 1.8359
2000	500	1j = 2.7266	2a=2.7266	2j = 1.3711	3a=2.2266	3j = 0.9102	4a=2.4766	4j = 1.0039
2000	50	1j = 5.0469	2a=3.5469	2j = 1.8516	3a=3.4219	3j = 1.5586	4a = 2.9297	4j = 2.2578
200	100	1j = 34.125	2a=37.625	2j = 12.5	3a=13.4375	3j = 6.8125	4a=12.8125	4j = 10.5938
200	10	1j = 50.625	2a=13.5625	2j = 8.7188	3a=12.6875	3j = 10.9062	4a=11.4062	4j = 20.8125
200	150	1j = 13.3125	2a=18.5625	2j = 7.2188	3a=12.8125	3j = 4.0156	4a = 8.7812	4j = 6.3438
200	1	1j = 35.375	2a = 41.75	2j = 8.1562	3a=16.6875	3j = 11.0312	4a=12.3438	4j = 9.6562
200	50	1j = 34.375	2a = 19.9688	2j = 19.4375	3a=11.9531	3j = 10.1562	4a=16.0625	4j = 7.2812
20	10	1j = 322.625	2a=147.5	2j = 28.625	3a = 38.625	3j = 58.625	4a = 75.25	4j = 56.75
20	1		2a = 156.625	2j = 32.625	3a = 80.25	3j = 29.125	4a = 149.25	4j = 59.25
300	100	1j = 27.125	2a = 17.6875	2j = 13.6875	3a=15.8125	3j = 11.0312	4a = 10.1562	4j = 20.8125
300	10	1j = 28.375	2a = 21.4375	2j = 13.8125	3a = 14.5625	3j = 9.9531	4a = 18.4375	4j = 11.6562
300	150	1j = 20.1875	2a = 24.4375	2j = 8.4688	3a=14.0625	3j = 7.4688	4a = 6.7812	4j = 11.9062
300	50	1j = 32.375	2a = 28.125	2j = 10.0312	3a=12.5625	3j = 8.0938	4a = 8.2812	4j = 8.2188
5000	1000	1j = 1.5703	2a = 2.3516	2j = 0.8789	3a=1.6016	3j = 0.7812	4a=1.4961	4j = 0.6152
5000	100	1j = 10.7812	2a = 6.4531	2j = 4.3281	3a = 4.2656	3j = 2.8516	4a = 3.7969	4j = 4.7969
5000	10	1j = 11.8438	2a = 6.1094	2j = 5.8594	3a = 4.5781	3j = 4.0469	4a=12.2188	4j = 4.5469
5000	150	1j = 8.5312	2a = 6.9531	2j = 4.2656	3a = 3.8281	3j = 2.2266	4a = 9.5938	4j = 3.1172
5000	1	1j = 12.8125	2a = 9.2188	2j = 3.2656	3a = 8.0312	3j = 3.6406	4a = 8.0938	4j = 3.9531
5000	500	1j = 3.1719	2a = 3.2969	2j = 1.543	3a=2.6016	3j = 1.3945	4a = 2.8672	4j = 1.1523
5000	50	1j = 10.0312	2a = 6.4062	2j = 4.6719	3a = 6.6562	3j = 3.8906	4a = 6.4688	4j = 3.0703
500	100	1j = 15.4062	2a = 7.3438	2j = 3.8594	3a=17.75	3j = 3.3906	4a = 7.4688	4j = 4.2031
500	10	1j = 14.9883	2a = 9.4766	2j = 7.0312	3a=17.6875	3j = 3.2031	4a = 7.6562	4j = 6.4688
500	150	1j = 14.6875	2a = 17.1875	2j = 7.1562	3a = 7.6562	3j = 4.9062	4a = 10.8438	4j = 7.2188
500	1	1j = 16.8125	2a = 10.0938	2j = 5.6406	3a=10.1562	3j = 4.0469	4a = 9.8438	4j = 3.3594
500	500	1j = 6.3438	2a = 3.6094	2j = 1.9141	3a = 2.7109	3j = 1.5508	4a = 2.3984	4j = 2.0859
500	50	1j = 20.5625	2a = 10.3438	2j = 5.2344	3a = 7.0312	3j = 5.0781	4a = 6.7188	4j = 7.4688
50	10	1j = 200.75	2a = 50.0213	2j = 41.25	3a = 79.9531	3j = 52.9531	4a = 142.25	4j = 36.625
50	1	1j = 59.875	2a = 128.25	2j = 64.25	3a = 31.125	3j = 73.25	4a = 40.9062	
50	50	1j = 31.625	2a = 19.9062	2j = 11.3438	3a=18.9062	3j = 8.0312	4a = 10.8125	4j = 16.5625