A Design Study Approach to Classical Control

Randal W. Beard Timothy W. McLain Brigham Young University

Updated: April 28, 2016

Homework A.9

- (a) When the controller for the single link robot arm is PD control, what is the system type? Characterize the steady state error when the reference input is a step, a ramp, and a parabola. How does this change if you add an integrator?
- (b) Consider the case where a constant disturbance acts at the input to the plant (for example gravity in this case). What is the steady state error to a constant input disturbance when the integrator is not present, and when it is present?

Solution

The closed loop system is shown in Figure 1.




Figure 1: Closed loop system for problem HW ??.13.

Without the integrator, the open-loop transfer function is given by

$$P(s)C(s) = \left(\frac{\frac{3}{m\ell^2}}{s(s + \frac{3b}{m\ell^2})}\right)(k_D s + k_P).$$

The system has one free integrator and is therefore type 1, which, from Table ?? implies that the tracking error when the input is a step is zero, and the tracking error when the input is a ramp is

$$\lim_{t \to \infty} e(t) = \frac{1}{M_v} = \frac{1}{\lim_{s \to 0} sP(s)C(s)} = \frac{1}{\frac{k_P}{h}} = \frac{b}{k_P}.$$

The tracking error when the input is a parabola, or higher order polynomial, is ∞ , meaning that $\theta(t)$ and $\theta^d(t)$ diverge as $t \to \infty$.

With the integrator, the open loop transfer function is

$$P(s)C(s) = \left(\frac{\frac{3}{m\ell^2}}{s(s + \frac{3b}{m\ell^2})}\right) \left(\frac{k_D s^2 + k_P s + k_I}{s}\right).$$

which has two free integrators and is therefore type 2. Therefore, from Table ?? the tracking error when the input is either a step or a ramp is zero, and the tracking error when the input is a parabola is

$$\lim_{t \to \infty} e(t) = \frac{1}{M_a} = \frac{1}{\lim_{s \to 0} s^2 P(s) C(s)} = \frac{1}{\frac{k_I}{b}} = \frac{b}{k_I}.$$

The tracking error when the input is t^3 or a higher order polynomial, is ∞ .

For the input disturbance, the transfer function from D(s) to E(s) is given by

$$E(s) = \frac{P(s)}{1 + P(s)C(s)}D(s).$$

Without the integrator, and when $D(s) = \frac{A}{s^{q+1}}$, the steady state error is given

by

$$\lim_{t \to \infty} e(t) = \lim_{s \to 0} \frac{P}{1 + PC} \frac{A}{s^q}$$

$$= \lim_{s \to 0} \left(\frac{\left(\frac{\frac{3}{m\ell^2}}{s(s + \frac{3b}{m\ell^2})}\right)}{1 + \left(\frac{\frac{3}{m\ell^2}}{s(s + \frac{3b}{m\ell^2})(k_D s + k_P)}\right)} \right) \left(\frac{A}{s^q}\right)$$

$$= \lim_{s \to 0} \left(\frac{\frac{3}{m\ell^2}}{s(s + \frac{3b}{m\ell^2})(k_D s + k_P)} \right) \left(\frac{A}{s^q}\right)$$

$$= \frac{A\frac{3}{m\ell^2}}{\frac{3k_P}{m\ell^2}}$$

$$= \frac{A}{k_P},$$

if q = 0. Therefore, to an input disturbance the system is type 0. The steady state error when a constant step of size A is placed on d(t) is $\frac{A}{k_P}$.

With the integrator, and when $D(s) = \frac{A}{s^{q+1}}$, the steady state error is given by

$$\lim_{t \to \infty} e(t) = \lim_{s \to 0} \frac{P}{1 + PC} \frac{A}{s^q}$$

$$= \lim_{s \to 0} \left(\frac{\left(\frac{\frac{3}{m\ell^2}}{s(s + \frac{3b}{m\ell^2})}\right)}{1 + \left(\frac{\frac{3}{m\ell^2}}{s(s + \frac{3b}{m\ell^2})}\right) \left(\frac{k_D s^2 + k_P s + k_I}{s}\right)} \right) \left(\frac{A}{s^q}\right)$$

$$= \lim_{s \to 0} \left(s \frac{\frac{3}{m\ell^2}}{s^2(s + \frac{3b}{m\ell^2}) + \frac{3}{m\ell^2}(k_D s^2 + k_P s + k_I)} \right) \left(\frac{A}{s^q}\right)$$

$$= \frac{A \frac{3}{m\ell^2}}{\frac{3k_I}{m\ell^2}}$$

$$= \frac{A}{k_I},$$

if q = 1. Therefore, to an input disturbance the system is type 1. The steady state error when d(t) is a constant step is zero, and the steady state error when d(t) is a ramp of slope of size A is $\frac{A}{k_I}$.