$$R1 \coloneqq 57$$
 $R2 \coloneqq 14$ $R3 \coloneqq 48$ $R4 \coloneqq 0$ $R5 \coloneqq 65$ $R6 \coloneqq 0$ $R7 \coloneqq 0$ $R8 \coloneqq 0$

$$Xl1 := 0$$
 $Xl2 := 0$ $Xl3 := 0$ $Xl4 := 31$ $Xl5 := 0$ $Xl6 := 29$ $Xl7 := 28$ $Xl8 := 36$

$$Xc1 := 83$$
 $Xc2 := 0$ $Xc3 := 23$ $Xc4 := 0$ $Xc5 := 0$ $Xc6 := 91$ $Xc7 := 0$ $Xc8 := 19$

$$E6M := 67 \quad E6a := 214$$

$$Z1 := R1 + 1j (-Xc1) = 57 - 83j$$

$$Z2 := R2 = 14$$

$$Z34 := R3 + 1j (Xl4 - Xc3) = 48 + 8i$$

$$Z56 := R5 + 1j (Xl6 - Xc6) = 65 - 62i$$

$$Z7 := 1j (Xl7) = 28i$$

$$Z8 := 1j (Xl8 - Xc8) = 17i$$

$$E := E6M \cdot e^{1j \cdot E6a^{\circ}} = -55.546 - 37.466j$$

$$A \coloneqq \begin{bmatrix} -1 & 0 & 0 & 1 & 0 & 1 \\ 1 & -1 & 0 & 0 & -1 & 0 \\ 0 & 1 & -1 & 0 & 0 & -1 \\ -Z1 & 0 & 0 & -Z56 & -Z7 & 0 \\ 0 & -Z2 & -Z34 & 0 & Z7 & 0 \\ Z1 & Z2 & 0 & 0 & 0 & Z8 \end{bmatrix}$$

$$B \coloneqq \begin{bmatrix} 0 \\ 0 \\ 0 \\ -E \\ 0 \\ 0 \end{bmatrix} \qquad B = \begin{bmatrix} 0 \\ 0 \\ 0 \\ 55.546 + 37.466i \\ 0 \\ 0 \end{bmatrix}$$

$$I \coloneqq A^{-1} \cdot B = \begin{bmatrix} 0.118 - 0.055i \\ 0.526 + 0.253i \\ -0.025 - 0.308i \\ -0.433 - 0.615i \\ -0.408 - 0.308i \\ 0.551 + 0.56i \end{bmatrix} \qquad \begin{bmatrix} I1 \\ I2 \\ I34 \\ I56 \\ I7 \\ I8 \end{bmatrix} \coloneqq I$$

$$I1 = 0.118 - 0.055i$$
 $I2 = 0.526 + 0.253i$ $I34 = -0.025 - 0.308i$

$$I56 = -0.433 - 0.615i$$
 $I7 = -0.408 - 0.308i$ $I8 = 0.551 + 0.56i$

 $Si := E \cdot \overline{156} = 47.129 - 17.941i$ Pi := Re(Si) = 47.129 Qi := Im(Si) = -17.941