

Power rails

VBAT 11.1 V from SW1: load 6.216 A typical, 22.516 A peak; source 35 A cont, 70 A peak; fuse 15 A

5V 5 V from U1: load 1.03 A typical, 5 A peak; source 5.5 A cont, 8 A peak

Fuses: F1 15 A (everything on VBAT), F2 2 A (branch regulator_5v). Branch fuses sit inline in the lead they protect.

Lever splices (star_ground, splice_vbat) are junctions of their nets.

Same net label or power symbol = same conductor. X = pin not connected.

Declared, no pins: MOTOR_DRIVER_1_CTRL_GND, MOTOR_DRIVER_2_CTRL_GND

Text to Robot generated from design.wiring

Title: **mecanum_robot: schematic**

15 parts, 37 nets, 52 wires, 2 rails

Size: A1	Rev: 2bc2ae50	Sheet 1 / 1
File: schematic.svg	KiCad symbol style	Id: 1/1