


Power rails

VBAT 11.1 V from SW1: load 10.916 A typical, 32.216 A peak; source 35 A cont, 70 A peak; fuse 20 A

5V 5 V from U1: load 0 A typical, 0 A peak; source 5.5 A cont, 8 A peak

Fuses: F1 20 A (everything on VBAT), F2 2 A (branch regulator_5v), F3 2 A (branch computer), F4 2 A (branch actuator_bus), F5 3 A (branch lf_coxa_actuator), F6 3 A (branch lm_coxa_actuator), F7 3 A (branch lr_coxa_actuator), F8 3 A (branch rr_coxa_actuator), F9 3 A (branch rm_coxa_actuator), F10 3 A (branch rf_coxa_actuator). Branch fuses sit inline in the lead they protect.

Lever splices (actuator_bus_hub, star_ground, splice_vbat) are junctions of their nets.

Same net label or power symbol = same conductor. X = pin not connected.

Declared, no pins: 5V

Text to Robot		generated from design.wiring
Title: **hexapod: schematic**		
30 parts, 10 nets, 73 wires, 2 rails		
Size: A1	Rev: 6a451e2c	Sheet 1 / 1
File: schematic.svg	KiCad symbol style	Id: 1/1